



20MHz_Low_QPSK_1@0 -29.12 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 18:39:57

20MHz_Low_QPSK_100@0 -30.21 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 18:41:00

20MHz_Middle_QPSK_1@0 -29.70 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 18:42:04

20MHz_Middle_QPSK_100@0 -29.74 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 18:43:08

20MHz_High_QPSK_1@0 -29.73 dBm



ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 18:44:14


20MHz_High_QPSK_100@0 -30.15 dBm



ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 18:45:18


B12 , Normal

1.4MHz_Low_QPSK_1@0 -34.65 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:00:26

1.4MHz_Low_QPSK_6@0 -34.53 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:01:16

1.4MHz_Middle_QPSK_1@0 -34.39 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:02:07

1.4MHz_Middle_QPSK_6@0 -34.14 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:02:57

1.4MHz_High_QPSK_1@0 -34.50 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:03:46

1.4MHz_High_QPSK_6@0 -33.13 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:04:36

3MHz_Low_QPSK_1@0 -34.87 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:06:01

3MHz_Low_QPSK_15@0 -33.47 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:06:53

3MHz_Middle_QPSK_1@0 -33.54 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:07:43

3MHz_Middle_QPSK_15@0 -32.67 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:08:35

3MHz_High_QPSK_1@0 -34.16 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:09:26

3MHz_High_QPSK_15@0 -33.61 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:10:16

5MHz_Low_QPSK_1@0 -34.23 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:11:43

5MHz_Low_QPSK_25@0 -32.72 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:12:35

5MHz_Middle_QPSK_1@0 -34.60 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:13:28

5MHz_Middle_QPSK_25@0 -34.74 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:14:21

5MHz_High_QPSK_1@0 -33.01 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:15:14

5MHz_High_QPSK_25@0 -30.28 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:16:05

10MHz_Low_QPSK_1@0 -34.76 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:17:31

10MHz_Low_QPSK_50@0 -31.51 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:18:24

10MHz_Middle_QPSK_1@0 -34.47 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:19:17

10MHz_Middle_QPSK_50@0 -33.20 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:20:08

10MHz_High_QPSK_1@0 -33.29 dBm



ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:20:59


10MHz_High_QPSK_50@0 -31.68 dBm



ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:21:50


B17 , Normal

5MHz_Low_QPSK_1@0 -33.40 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:22:49

5MHz_Low_QPSK_25@0 -33.88 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:23:39

5MHz_Middle_QPSK_1@0 -33.26 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:24:31

5MHz_Middle_QPSK_25@0 -34.40 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:25:23

5MHz_High_QPSK_1@0 -34.05 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:26:15

5MHz_High_QPSK_25@0 -33.96 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:27:09

10MHz_Low_QPSK_1@0 -34.19 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:28:36

10MHz_Low_QPSK_50@0 -31.94 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:29:28

10MHz_Middle_QPSK_1@0 -35.08 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:30:20

10MHz_Middle_QPSK_50@0 -32.42 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:31:11

10MHz_High_QPSK_1@0 -34.35 dBm



ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:32:05


10MHz_High_QPSK_50@0 -32.83 dBm



ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 9.MAY.2024 00:32:55


B38 , Normal

5MHz_Low_QPSK_1@0 -29.69 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 11.MAY.2024 13:27:35

5MHz_Low_QPSK_25@0 -29.74 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 11.MAY.2024 13:31:11

5MHz_Middle_QPSK_1@0 -28.79 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 11.MAY.2024 13:32:22

5MHz_Middle_QPSK_25@0 -29.99 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 11.MAY.2024 13:34:06

5MHz_High_QPSK_1@0 -30.00 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 11.MAY.2024 13:35:19

5MHz_High_QPSK_25@0 -29.20 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 11.MAY.2024 13:38:41

10MHz_Low_QPSK_1@0 -29.39 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 11.MAY.2024 13:40:14

10MHz_Low_QPSK_50@0 -30.50 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 11.MAY.2024 13:44:27

10MHz_Middle_QPSK_1@0 -29.65 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 11.MAY.2024 13:45:38

10MHz_Middle_QPSK_50@0 -29.51 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 11.MAY.2024 13:52:14

10MHz_High_QPSK_1@0 -28.81 dBm



ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 11.MAY.2024 13:53:20


10MHz_High_QPSK_50@0 -28.64 dBm



ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 11.MAY.2024 13:54:21


B66 , Normal

1.4MHz_Low_QPSK_1@0 -33.48 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 22:59:30

1.4MHz_Low_QPSK_6@0 -33.69 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:00:21

1.4MHz_Middle_QPSK_1@0 -33.40 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:01:14

1.4MHz_Middle_QPSK_6@0 -33.56 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:02:09

1.4MHz_High_QPSK_1@0 -32.93 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:03:03

1.4MHz_High_QPSK_6@0 -32.96 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:03:58

5MHz_Low_QPSK_1@0 -32.75 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:11:17

5MHz_Low_QPSK_25@0 -33.78 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:12:10

5MHz_Middle_QPSK_1@0 -33.36 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:13:04

5MHz_Middle_QPSK_25@0 -32.42 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:13:57

5MHz_High_QPSK_1@0 -32.44 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:14:49

5MHz_High_QPSK_25@0 -32.39 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:15:46

15MHz_Low_QPSK_1@0 -33.51 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:23:06

15MHz_Low_QPSK_75@0 -33.11 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:23:59

15MHz_Middle_QPSK_1@0 -32.83 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:24:55

15MHz_Middle_QPSK_75@0 -32.41 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:25:48

15MHz_High_QPSK_1@0 -32.51 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:26:42

15MHz_High_QPSK_75@0 -32.52 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:27:35

20MHz_Low_QPSK_1@0 -33.46 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:29:01

20MHz_Low_QPSK_100@0 -33.12 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:29:53

20MHz_Middle_QPSK_1@0 -33.01 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:30:48

20MHz_Middle_QPSK_100@0 -33.37 dBm




ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:31:41

20MHz_High_QPSK_1@0 -33.02 dBm



ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:32:36

20MHz_High_QPSK_100@0 -32.46 dBm



ProjectNo.:2403S72396E-RF Tester:Arthur Su
Date: 8.MAY.2024 23:33:30