





n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB75@0

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@0





n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105




n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0


n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@0




n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0




n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132




n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0




n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@0




n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0



n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161




n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 16:29:43

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 16:30:12

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 16:51:59

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 16:31:17

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 16:31:40

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB1@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 12:58:14


n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0




n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@216




n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB216@0




n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@0




n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB243@0




n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@244




n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB243@0




n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0




n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB270@0




n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@272



n78_3
n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0





n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB24@0




n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM QPSK_RB1@23


n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM QPSK_RB24@0




n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@0




n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB36@0



n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB1@37





n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB36@0





n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB1@0

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB50@0





n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM QPSK_RB1@50

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM QPSK_RB50@0




n78_3_25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0

n78_3_25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB64@0




n78_3_25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@64




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 14:45:04

n78_3_25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB64@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 14:45:29

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 14:50:21

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB75@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 14:50:47

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@77




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 14:51:17

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB75@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 14:51:42


n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0




n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0




n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB1@105




n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB100@0




n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0



n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0




n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB1@132




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 15:00:24

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 16:54:33

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 16:32:36

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 16:33:00

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB1@161




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 16:45:28

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 16:34:03


n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0




n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB180@0




n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@188




n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB180@0




n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@0



n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB216@0




n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB1@216




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 15:14:33

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 15:15:00

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB1@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 15:18:25

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 17:02:25

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB1@244




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 17:02:52

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 17:03:15

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0




ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 17:07:23

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0



ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 17:07:53

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@272



ProjectNo.:2602R09298E-RF Tester:Loge Long
Date: 13.APR.2026 17:08:41