






Plot on Channel 6865 MHz



Plot on Channel 6945 MHz




Plot on Channel 7025 MHz






EUT Mode 802.11be EHT80 Puncture20 1

Plot on Channel 6145 MHz




05:19:48 PM 12/20/2023

Plot on Channel 6305 MHz




05:17:16 PM 12/20/2023

Plot on Channel 6385 MHz



05:55:48 PM 12/20/2023


Plot on Channel 6465 MHz



06:12:56 PM 12/20/2023




Plot on Channel 6545 MHz




06:23:00 PM 12/20/2023

Plot on Channel 6625 MHz




06:28:14 PM 12/20/2023

Plot on Channel 6705 MHz



06:51:51 PM 12/20/2023


Plot on Channel 6785 MHz




07:02:33 PM 12/20/2023




Plot on Channel 6865 MHz



Plot on Channel 6945 MHz



Plot on Channel 7025 MHz







EUT Mode

802.11be EHT160 Full RU


Plot on Channel 6185 MHz




Plot on Channel 6345 MHz



Plot on Channel 6505 MHz




Plot on Channel 6665 MHz






Plot on Channel 6825 MHz



Plot on Channel 6985 MHz






EUT Mode


802.11be EHT160 106OFDMA RU16

Plot on Channel 6185 MHz




12:20:35 AM 12/20/2023

Plot on Channel 6345 MHz




12:30:20 AM 12/20/2023

Plot on Channel 6505 MHz



12:38:43 AM 12/20/2023


Plot on Channel 6665 MHz




12:42:39 AM 12/20/2023



Plot on Channel 6825 MHz



Plot on Channel 6985 MHz







EUT Mode

802.11be EHT160 Puncture20 1


Plot on Channel 6185 MHz




Plot on Channel 6345 MHz



Plot on Channel 6505 MHz




Plot on Channel 6665 MHz






Plot on Channel 6825 MHz




Plot on Channel 6985 MHz






EUT Mode 802.11be EHT160 Puncture40 1

Plot on Channel 6185 MHz




11:16:31 PM 12/20/2023

Plot on Channel 6345 MHz




11:24:54 PM 12/20/2023

Plot on Channel 6505 MHz



11:37:43 PM 12/20/2023


Plot on Channel 6665 MHz




11:46:11 PM 12/20/2023



Plot on Channel 6825 MHz




Plot on Channel 6985 MHz






EUT Mode 802.11be EHT320 Full RU

Plot on Channel 6265 MHz




06:09:06 PM 12/18/2023

Plot on Channel 6425 MHz




06:14:17 PM 12/18/2023

Plot on Channel 6585 MHz



06:22:31 PM 12/18/2023


Plot on Channel 6745 MHz



06:29:27 PM 12/18/2023



Plot on Channel 6905 MHz







EUT Mode

802.11be EHT320 242OFDMA RU16


Plot on Channel 6265 MHz




Plot on Channel 6425 MHz



Plot on Channel 6585 MHz




Plot on Channel 6745 MHz





Plot on Channel 6905 MHz






EUT Mode


802.11be EHT320 Puncture40 1

Plot on Channel 6265 MHz




12:23:50 AM 12/21/2023

Plot on Channel 6425 MHz




12:29:13 AM 12/21/2023

Plot on Channel 6585 MHz



12:39:22 AM 12/21/2023


Plot on Channel 6745 MHz



12:45:21 AM 12/21/2023



Plot on Channel 6905 MHz






EUT Mode


802.11be EHT320 Puncture80 1

Plot on Channel 6265 MHz




01:04:06 AM 12/21/2023

Plot on Channel 6425 MHz




01:08:10 AM 12/21/2023

Plot on Channel 6585 MHz



01:12:16 AM 12/21/2023

Plot on Channel 6745 MHz



01:16:44 AM 12/21/2023



Plot on Channel 6905 MHz

