U-NII-2C, 802.11ax HE40, Channel No.: 118

U-NII-2C, 802.11ax HE20, Channel No.: 140

U-NII-2C, 802.11ax HE40, Channel No.: 134



U-NII-2C, 802.11ax HE20, Channel No.: 144

U-NII-2C, 802.11ax HE40, Channel No.: 142



U-NII-2C, 802.11ax HE80, Channel No.: 106

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11ax HE80, Channel No.: 122

U-NII-2C, 802.11ax HE80, Channel No.: 138

U-NII-3, 802.11a, Channel No.: 149



U-NII-3, 802.11n HT20, Channel No.: 149

U-NII-3, 802.11a, Channel No.: 157

U-NII-3, 802.11n HT20, Channel No.: 157

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-3, 802.11a, Channel No.: 165



U-NII-3, 802.11n HT20, Channel No.: 165

U-NII-3, 802.11n HT40, Channel No.: 151

U-NII-3, 802.11ac VHT20, Channel No.: 149

U-NII-3, 802.11n HT40, Channel No.: 159



U-NII-3, 802.11ac VHT20, Channel No.: 157

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-3, 802.11ac VHT40, Channel No.: 151

U-NII-3, 802.11ac VHT20, Channel No.: 165

U-NII-3, 802.11ac VHT40, Channel No.: 159



U-NII-3, 802.11ac VHT80, Channel No.: 155

U-NII-3, 802.11ax HE20, Channel No.: 149



U-NII-3, 802.11ax HE40, Channel No.: 151

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-3, 802.11ax HE20, Channel No.: 157

U-NII-3, 802.11ax HE40, Channel No.: 159

U-NII-3, 802.11ax HE20, Channel No.: 165



U-NII-3, 802.11ax HE80, Channel No.: 155

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

Antenna 3

U-NII-1, 802.11a, Channel No.: 36

U-NII-1, 802.11n HT20, Channel No.: 36



U-NII-1, 802.11a, Channel No.: 40

U-NII-1, 802.11n HT20, Channel No.: 40

U-NII-1, 802.11a, Channel No.: 48

U-NII-1, 802.11n HT20, Channel No.: 48

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-1, 802.11n HT40, Channel No.: 38

U-NII-1, 802.11ac VHT20, Channel No.: 36

U-NII-1, 802.11n HT40, Channel No.: 46



U-NII-1, 802.11ac VHT20, Channel No.: 40



U-NII-1, 802.11ac VHT40, Channel No.: 38

U-NII-1, 802.11ac VHT20, Channel No.: 48

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-1, 802.11ac VHT40, Channel No.: 46



U-NII-1, 802.11ac VHT80, Channel No.: 42

U-NII-1, 802.11ax HE20, Channel No.: 36

U-NII-1, 802.11ax HE40, Channel No.: 38

U-NII-1, 802.11ax HE20, Channel No.: 40

U-NII-1, 802.11ax HE40, Channel No.: 46

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-1, 802.11ax HE20, Channel No.: 48



U-NII-1, 802.11ax HE80, Channel No.: 42

U-NII-2A, 802.11a, Channel No.: 52

U-NII-2A, 802.11n HT20, Channel No.: 52

U-NII-2A, 802.11a, Channel No.: 60

U-NII-2A, 802.11n HT20, Channel No.: 60

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2A, 802.11a, Channel No.: 64

U-NII-2A, 802.11n HT20, Channel No.: 64

U-NII-2A, 802.11n HT40, Channel No.: 54

U-NII-2A, 802.11ac VHT20, Channel No.:52

U-NII-2A, 802.11n HT40, Channel No.: 62



U-NII-2A, 802.11ac VHT20, Channel No.: 60

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2A, 802.11ac VHT40, Channel No.: 54

U-NII-2A, 802.11ac VHT20, Channel No.: 64

U-NII-2A, 802.11ac VHT40, Channel No.: 62

U-NII-2A, 802.11ac VHT80, Channel No.: 58

U-NII-2A, 802.11ax HE20, Channel No.:52

U-NII-2A, 802.11ax HE40, Channel No.: 54

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2A, 802.11ax HE20, Channel No.: 60

U-NII-2A, 802.11ax HE40, Channel No.: 62

U-NII-2A, 802.11ax HE20, Channel No.: 64

U-NII-2A, 802.11ax HE80, Channel No.: 58

U-NII-2C, 802.11a, Channel No.: 100

U-NII-2C, 802.11n HT20, Channel No.: 100

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11a, Channel No.: 120

U-NII-2C, 802.11n HT20, Channel No.: 120

U-NII-2C, 802.11a, Channel No.: 140

U-NII-2C, 802.11n HT20, Channel No.: 140

U-NII-2C, 802.11a, Channel No.: 144

U-NII-2C, 802.11n HT20, Channel No.: 144

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11n HT40, Channel No.: 102

U-NII-2C, 802.11ac VHT20, Channel No.: 100

U-NII-2C, 802.11n HT40, Channel No.: 118

U-NII-2C, 802.11ac VHT20, Channel No.: 120

U-NII-2C, 802.11n HT40, Channel No.: 134



U-NII-2C, 802.11ac VHT20, Channel No.: 140

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11n HT40, Channel No.: 142

U-NII-2C, 802.11ac VHT20, Channel No.: 144

U-NII-2C, 802.11ac VHT40, Channel No.: 102

U-NII-2C, 802.11ac VHT80, Channel No.: 106



U-NII-2C, 802.11ac VHT40, Channel No.: 118



U-NII-2C, 802.11ac VHT80, Channel No.: 122

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11ac VHT40, Channel No.: 134

U-NII-2C, 802.11ac VHT80, Channel No.: 138

U-NII-2C, 802.11ac VHT40, Channel No.: 142

U-NII-2C, 802.11ax HE20, Channel No.: 100

U-NII-2C, 802.11ax HE40, Channel No.: 102



U-NII-2C, 802.11ax HE20, Channel No.: 120

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11ax HE40, Channel No.: 118



U-NII-2C, 802.11ax HE20, Channel No.: 140

U-NII-2C, 802.11ax HE40, Channel No.: 134



U-NII-2C, 802.11ax HE20, Channel No.: 144

U-NII-2C, 802.11ax HE40, Channel No.: 142



U-NII-2C, 802.11ax HE80, Channel No.: 106

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11ax HE80, Channel No.: 122

U-NII-2C, 802.11ax HE80, Channel No.: 138

U-NII-3, 802.11a, Channel No.: 149

U-NII-3, 802.11n HT20, Channel No.: 149

U-NII-3, 802.11a, Channel No.: 157

U-NII-3, 802.11n HT20, Channel No.: 157

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-3, 802.11a, Channel No.: 165

U-NII-3, 802.11n HT20, Channel No.: 165

U-NII-3, 802.11n HT40, Channel No.: 151



U-NII-3, 802.11ac VHT20, Channel No.: 149

U-NII-3, 802.11n HT40, Channel No.: 159



U-NII-3, 802.11ac VHT20, Channel No.: 157

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-3, 802.11ac VHT40, Channel No.: 151



U-NII-3, 802.11ac VHT20, Channel No.: 165

U-NII-3, 802.11ac VHT40, Channel No.: 159



U-NII-3, 802.11ac VHT80, Channel No.: 155

U-NII-3, 802.11ax HE20, Channel No.: 149

U-NII-3, 802.11ax HE40, Channel No.: 151

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-3, 802.11ax HE20, Channel No.: 157

U-NII-3, 802.11ax HE40, Channel No.: 159

U-NII-3, 802.11ax HE20, Channel No.: 165

U-NII-3, 802.11ax HE80, Channel No.: 155

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

Antenna 4

U-NII-1, 802.11a, Channel No.: 36

U-NII-1, 802.11n HT20, Channel No.: 36

U-NII-1, 802.11a, Channel No.: 40

U-NII-1, 802.11n HT20, Channel No.: 40

U-NII-1, 802.11a, Channel No.: 48

U-NII-1, 802.11n HT20, Channel No.: 48

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-1, 802.11n HT40, Channel No.: 38

U-NII-1, 802.11ac VHT20, Channel No.: 36



U-NII-1, 802.11n HT40, Channel No.: 46



U-NII-1, 802.11ac VHT20, Channel No.: 40



U-NII-1, 802.11ac VHT40, Channel No.: 38

U-NII-1, 802.11ac VHT20, Channel No.: 48

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-1, 802.11ac VHT40, Channel No.: 46

U-NII-1, 802.11ac VHT80, Channel No.: 42

U-NII-1, 802.11ax HE20, Channel No.: 36



U-NII-1, 802.11ax HE40, Channel No.: 38

U-NII-1, 802.11ax HE20, Channel No.: 40

U-NII-1, 802.11ax HE40, Channel No.: 46

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-1, 802.11ax HE20, Channel No.: 48

U-NII-1, 802.11ax HE80, Channel No.: 42

U-NII-2A, 802.11a, Channel No.: 52

U-NII-2A, 802.11n HT20, Channel No.: 52

U-NII-2A, 802.11a, Channel No.: 60

U-NII-2A, 802.11n HT20, Channel No.: 60

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2A, 802.11a, Channel No.: 64

U-NII-2A, 802.11n HT20, Channel No.: 64

U-NII-2A, 802.11n HT40, Channel No.: 54

U-NII-2A, 802.11ac VHT20, Channel No.:52

U-NII-2A, 802.11n HT40, Channel No.: 62

U-NII-2A, 802.11ac VHT20, Channel No.: 60

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2A, 802.11ac VHT40, Channel No.: 54

U-NII-2A, 802.11ac VHT20, Channel No.: 64

U-NII-2A, 802.11ac VHT40, Channel No.: 62

U-NII-2A, 802.11ac VHT80, Channel No.: 58

U-NII-2A, 802.11ax HE20, Channel No.:52



U-NII-2A, 802.11ax HE40, Channel No.: 54

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2A, 802.11ax HE20, Channel No.: 60



U-NII-2A, 802.11ax HE40, Channel No.: 62

U-NII-2A, 802.11ax HE20, Channel No.: 64

U-NII-2A, 802.11ax HE80, Channel No.: 58

U-NII-2C, 802.11a, Channel No.: 100

U-NII-2C, 802.11n HT20, Channel No.: 100

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11a, Channel No.: 120

U-NII-2C, 802.11n HT20, Channel No.: 120

U-NII-2C, 802.11a, Channel No.: 140

U-NII-2C, 802.11n HT20, Channel No.: 140

U-NII-2C, 802.11a, Channel No.: 144

U-NII-2C, 802.11n HT20, Channel No.: 144

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11n HT40, Channel No.: 102

U-NII-2C, 802.11ac VHT20, Channel No.: 100

U-NII-2C, 802.11n HT40, Channel No.: 118

U-NII-2C, 802.11ac VHT20, Channel No.: 120

U-NII-2C, 802.11n HT40, Channel No.: 134



U-NII-2C, 802.11ac VHT20, Channel No.: 140



This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11n HT40, Channel No.: 142

U-NII-2C, 802.11ac VHT20, Channel No.: 144

U-NII-2C, 802.11ac VHT40, Channel No.: 102

U-NII-2C, 802.11ac VHT80, Channel No.: 106

U-NII-2C, 802.11ac VHT40, Channel No.: 118

U-NII-2C, 802.11ac VHT80, Channel No.: 122

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11ac VHT40, Channel No.: 134

U-NII-2C, 802.11ac VHT80, Channel No.: 138

U-NII-2C, 802.11ac VHT40, Channel No.: 142

U-NII-2C, 802.11ax HE20, Channel No.: 100

U-NII-2C, 802.11ax HE40, Channel No.: 102

U-NII-2C, 802.11ax HE20, Channel No.: 120

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11ax HE40, Channel No.: 118

U-NII-2C, 802.11ax HE20, Channel No.: 140

U-NII-2C, 802.11ax HE40, Channel No.: 134

U-NII-2C, 802.11ax HE20, Channel No.: 144

U-NII-2C, 802.11ax HE40, Channel No.: 142



U-NII-2C, 802.11ax HE80, Channel No.: 106

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11ax HE80, Channel No.: 122

U-NII-2C, 802.11ax HE80, Channel No.: 138

U-NII-3, 802.11a, Channel No.: 149

U-NII-3, 802.11n HT20, Channel No.: 149

U-NII-3, 802.11a, Channel No.: 157



U-NII-3, 802.11n HT20, Channel No.: 157

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-3, 802.11a, Channel No.: 165



U-NII-3, 802.11n HT20, Channel No.: 165

U-NII-3, 802.11n HT40, Channel No.: 151

U-NII-3, 802.11ac VHT20, Channel No.: 149

U-NII-3, 802.11n HT40, Channel No.: 159



U-NII-3, 802.11ac VHT20, Channel No.: 157

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-3, 802.11ac VHT40, Channel No.: 151

U-NII-3, 802.11ac VHT20, Channel No.: 165

U-NII-3, 802.11ac VHT40, Channel No.: 159

U-NII-3, 802.11ac VHT80, Channel No.: 155

U-NII-3, 802.11ax HE20, Channel No.: 149

U-NII-3, 802.11ax HE40, Channel No.: 151

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-3, 802.11ax HE20, Channel No.: 157

U-NII-3, 802.11ax HE40, Channel No.: 159

U-NII-3, 802.11ax HE20, Channel No.: 165

U-NII-3, 802.11ax HE80, Channel No.: 155

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

MIMO with Beamforming

Antenna 1

U-NII-1, 802.11a, Channel No.: 36

U-NII-1, 802.11n HT20, Channel No.: 36

U-NII-1, 802.11a, Channel No.: 40

U-NII-1, 802.11n HT20, Channel No.: 40

U-NII-1, 802.11a, Channel No.: 48

U-NII-1, 802.11n HT20, Channel No.: 48



This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-1, 802.11n HT40, Channel No.: 38

U-NII-1, 802.11ac VHT20, Channel No.: 36

U-NII-1, 802.11n HT40, Channel No.: 46



U-NII-1, 802.11ac VHT20, Channel No.: 40

U-NII-1, 802.11ac VHT40, Channel No.: 38

U-NII-1, 802.11ac VHT20, Channel No.: 48



This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-1, 802.11ac VHT40, Channel No.: 46

U-NII-1, 802.11ac VHT80, Channel No.: 42

U-NII-1, 802.11ax HE20, Channel No.: 36

U-NII-1, 802.11ax HE40, Channel No.: 38

U-NII-1, 802.11ax HE20, Channel No.: 40

U-NII-1, 802.11ax HE40, Channel No.: 46

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-1, 802.11ax HE20, Channel No.: 48

U-NII-1, 802.11ax HE80, Channel No.: 42

U-NII-2A, 802.11a, Channel No.: 52

U-NII-2A, 802.11n HT20, Channel No.: 52

U-NII-2A, 802.11a, Channel No.: 60



U-NII-2A, 802.11n HT20, Channel No.: 60

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2A, 802.11a, Channel No.: 64

U-NII-2A, 802.11n HT20, Channel No.: 64

U-NII-2A, 802.11n HT40, Channel No.: 54

U-NII-2A, 802.11ac VHT20, Channel No.:52

U-NII-2A, 802.11n HT40, Channel No.: 62



U-NII-2A, 802.11ac VHT20, Channel No.: 60

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2A, 802.11ac VHT40, Channel No.: 54

U-NII-2A, 802.11ac VHT20, Channel No.: 64

U-NII-2A, 802.11ac VHT40, Channel No.: 62

U-NII-2A, 802.11ac VHT80, Channel No.: 58

U-NII-2A, 802.11ax HE20, Channel No.:52

U-NII-2A, 802.11ax HE40, Channel No.: 54

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2A, 802.11ax HE20, Channel No.: 60

U-NII-2A, 802.11ax HE40, Channel No.: 62

U-NII-2A, 802.11ax HE20, Channel No.: 64

U-NII-2A, 802.11ax HE80, Channel No.: 58

U-NII-2C, 802.11a, Channel No.: 100

U-NII-2C, 802.11n HT20, Channel No.: 100

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11a, Channel No.: 120

U-NII-2C, 802.11n HT20, Channel No.: 120

U-NII-2C, 802.11a, Channel No.: 140

U-NII-2C, 802.11n HT20, Channel No.: 140

U-NII-2C, 802.11a, Channel No.: 144

U-NII-2C, 802.11n HT20, Channel No.: 144

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11n HT40, Channel No.: 102

U-NII-2C, 802.11ac VHT20, Channel No.: 100

U-NII-2C, 802.11n HT40, Channel No.: 118

U-NII-2C, 802.11ac VHT20, Channel No.: 120

U-NII-2C, 802.11n HT40, Channel No.: 134



U-NII-2C, 802.11ac VHT20, Channel No.: 140

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11n HT40, Channel No.: 142

U-NII-2C, 802.11ac VHT20, Channel No.: 144

U-NII-2C, 802.11ac VHT40, Channel No.: 102

U-NII-2C, 802.11ac VHT80, Channel No.: 106

U-NII-2C, 802.11ac VHT40, Channel No.: 118

U-NII-2C, 802.11ac VHT80, Channel No.: 122

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11ac VHT40, Channel No.: 134

U-NII-2C, 802.11ac VHT80, Channel No.: 138

U-NII-2C, 802.11ac VHT40, Channel No.: 142

U-NII-2C, 802.11ax HE20, Channel No.: 100

U-NII-2C, 802.11ax HE40, Channel No.: 102



U-NII-2C, 802.11ax HE20, Channel No.: 120

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11ax HE40, Channel No.: 118

U-NII-2C, 802.11ax HE20, Channel No.: 140

U-NII-2C, 802.11ax HE40, Channel No.: 134

U-NII-2C, 802.11ax HE20, Channel No.: 144

U-NII-2C, 802.11ax HE40, Channel No.: 142



U-NII-2C, 802.11ax HE80, Channel No.: 106

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2C, 802.11ax HE80, Channel No.: 122

U-NII-2C, 802.11ax HE80, Channel No.: 138

U-NII-3, 802.11a, Channel No.: 149

U-NII-3, 802.11n HT20, Channel No.: 149

U-NII-3, 802.11a, Channel No.: 157

U-NII-3, 802.11n HT20, Channel No.: 157

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-3, 802.11a, Channel No.: 165

U-NII-3, 802.11n HT20, Channel No.: 165

U-NII-3, 802.11n HT40, Channel No.: 151



U-NII-3, 802.11ac VHT20, Channel No.: 149

U-NII-3, 802.11n HT40, Channel No.: 159



U-NII-3, 802.11ac VHT20, Channel No.: 157

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-3, 802.11ac VHT40, Channel No.: 151

U-NII-3, 802.11ac VHT20, Channel No.: 165

U-NII-3, 802.11ac VHT40, Channel No.: 159

U-NII-3, 802.11ac VHT80, Channel No.: 155

U-NII-3, 802.11ax HE20, Channel No.: 149

U-NII-3, 802.11ax HE40, Channel No.: 151

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-3, 802.11ax HE20, Channel No.: 157

U-NII-3, 802.11ax HE40, Channel No.: 159

U-NII-3, 802.11ax HE20, Channel No.: 165

U-NII-3, 802.11ax HE80, Channel No.: 155

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

Antenna 2

U-NII-1, 802.11a, Channel No.: 36

U-NII-1, 802.11n HT20, Channel No.: 36



U-NII-1, 802.11a, Channel No.: 40

U-NII-1, 802.11n HT20, Channel No.: 40

U-NII-1, 802.11a, Channel No.: 48

U-NII-1, 802.11n HT20, Channel No.: 48

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-1, 802.11n HT40, Channel No.: 38

U-NII-1, 802.11ac VHT20, Channel No.: 36

U-NII-1, 802.11n HT40, Channel No.: 46



U-NII-1, 802.11ac VHT20, Channel No.: 40

U-NII-1, 802.11ac VHT40, Channel No.: 38

U-NII-1, 802.11ac VHT20, Channel No.: 48

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-1, 802.11ac VHT40, Channel No.: 46

U-NII-1, 802.11ac VHT80, Channel No.: 42

U-NII-1, 802.11ax HE20, Channel No.: 36



U-NII-1, 802.11ax HE40, Channel No.: 38

U-NII-1, 802.11ax HE20, Channel No.: 40

U-NII-1, 802.11ax HE40, Channel No.: 46

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-1, 802.11ax HE20, Channel No.: 48

U-NII-1, 802.11ax HE80, Channel No.: 42

U-NII-2A, 802.11a, Channel No.: 52

U-NII-2A, 802.11n HT20, Channel No.: 52

U-NII-2A, 802.11a, Channel No.: 60

U-NII-2A, 802.11n HT20, Channel No.: 60

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2A, 802.11a, Channel No.: 64

U-NII-2A, 802.11n HT20, Channel No.: 64

U-NII-2A, 802.11n HT40, Channel No.: 54

U-NII-2A, 802.11ac VHT20, Channel No.:52

U-NII-2A, 802.11n HT40, Channel No.: 62



U-NII-2A, 802.11ac VHT20, Channel No.: 60

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2A, 802.11ac VHT40, Channel No.: 54

U-NII-2A, 802.11ac VHT20, Channel No.: 64

U-NII-2A, 802.11ac VHT40, Channel No.: 62

U-NII-2A, 802.11ac VHT80, Channel No.: 58

U-NII-2A, 802.11ax HE20, Channel No.:52

U-NII-2A, 802.11ax HE40, Channel No.: 54

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.

U-NII-2A, 802.11ax HE20, Channel No.: 60



U-NII-2A, 802.11ax HE40, Channel No.: 62

U-NII-2A, 802.11ax HE20, Channel No.: 64

U-NII-2A, 802.11ax HE80, Channel No.: 58

U-NII-2C, 802.11a, Channel No.: 100

U-NII-2C, 802.11n HT20, Channel No.: 100

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.