

INTERTEK TESTING SERVICE

Report No.: 15080414HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AE3ABTS015PC



IC: 20421-BTS015PC

INTERTEK TESTING SERVICE

Report No.: 15080414HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AE3ABTS015PC



IC: 20421-BTS015PC

INTERTEK TESTING SERVICE

Report No.: 15080414HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AE3ABTS015PC


IC: 20421-BTS015PC

INTERTEK TESTING SERVICE

Report No.: 15080414HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AE3ABTS015PC



IC: 20421-BTS015PC

INTERTEK TESTING SERVICE

Report No.: 15080414HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AE3ABTS015PC


IC: 20421-BTS015PC

INTERTEK TESTING SERVICE

Report No.: 15080414HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AE3ABTS015PC

IC: 20421-BTS015PC