

02/29/2016

Equipment Authorisation Division
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Subject: Class II permissive change Request
FCC ID: 2AE3L-MD14322

Granted on: 06/18/2015

To whom may concern:

Pursuant to CRF Section 2.1043, Youngs Watch Co., Ltd. requests a Class II permissive change to update the filing.

Change list:


1, MCU Type;

Before: IC_MS-F1407, MCU 16bit, Dice
Change to: IC_MS-F1507, MCU 16bit, Dice


2, PCB Layout;

Before: PCB_MD14322, FR4, 0.6mm, Rev.2
Change to: PCB_MD14322A, FR4, 0.6mm, Rev.0

a1--- MD14322, Rev.2 TopLayer (Old PCB);
a2--- MD14322A, Rev.0 TopLayer (New PCB);



b1--- MD14322, Rev.2 BottomLayer (Old PCB);
b2--- MD14322A, Rev.0 BottomLayer (New PCB);



3, For this time modified, only the MCU and PCB layout change, No any other changes occur; The LCD display、BLE Module、Product function are same. RF performance, parameter are same, no any RF change occur.

Sincerely,

Signature:

Name: Tom Chang

Company Name: Youngs Watch Co., Ltd.