


Appendix 1

Test Results


Peak Output Power

Tx frequency: 2402 MHz




Date: 30.JUL.2019 13:35:37

Tx frequency: 2441 MHz



Date: 30.JUL.2019 13:36:24

Tx frequency: 2480 MHz



Date: 30.JUL.2019 13:36:59


20dB Bandwidth

Tx frequency: 2402MHz




Date: 30.JUL.2019 11:21:15

Tx frequency: 2441MHz




Date: 30.JUL.2019 11:19:05

Tx frequency: 2480MHz




Date: 30.JUL.2019 11:18:00

Carrier Frequency Separation




Date: 30.JUL.2019 13:29:35

Number of hopping channels




Date: 30.JUL.2019 13:32:04




Date: 30.JUL.2019 13:34:09

Dwell Time




Date: 30.JUL.2019 13:41:51




Date: 30.JUL.2019 13:43:59

Spurious Emissions - Conducted


Tx frequency: 2402MHz




Date: 30.JUL.2019 13:46:16



Date: 30.JUL.2019 13:51:02




Date: 30.JUL.2019 13:57:09




Date: 30.JUL.2019 13:57:56

Tx frequency: 2402MHz (hopping off)




Date: 30.JUL.2019 11:24:07

Tx frequency: 2402MHz (hopping on)




Date: 30.JUL.2019 13:17:18


Tx frequency: 2441 MHz




Date: 30.JUL.2019 13:47:30



Date: 30.JUL.2019 13:52:59




Date: 30.JUL.2019 13:55:50




Date: 30.JUL.2019 13:59:10


Tx frequency: 2480 MHz




Date: 30.JUL.2019 13:48:15



Date: 30.JUL.2019 13:54:01




Date: 30.JUL.2019 13:54:59




Date: 30.JUL.2019 14:00:42

Tx frequency: 2480 MHz (hopping off)



Date: 30.JUL.2019 13:24:09

Tx frequency: 2480 MHz (hopping on)



Date: 30.JUL.2019 13:12:36