



Model: IM-301

IntelliMeter

UL File: E470522

Contains FCC ID: 2AECN300

Input: 120-277VAC, 50/60Hz

Output: 24VDC, 150mA (Class 2)

Ballast or Incandescent Load: 20A

Motor Load: 1HP

UL 2043 Plenum Rated

Enclosed Energy Management Equipment: UL 9034




Ibis NETWORKS



BLK (Line)

WHT (Neutral)

RED (Load)



RED (24VDC)

BLK (Common)

BLU (Occupancy)

ORG (Switch)







Model: IM-301
IntelliMeter

UL File: E470522

Contains FCC ID: 2AECN300

Input: 120-277VAC, 50/60Hz

Output: 24VDC, 150mA (Class 2)

Ballast or Incandescent Load: 20A

Motor Load: 1HP

UL 2043 Plenum Rated

Enclosed Energy Management Equipment: UL 9034



ibis
NETWORKS





Model: IM-301
IntelliMeter

UL File: E470522
Contains FCC ID: ZAECH300
Input: 120-277VAC, 50/60Hz
Output: 24VDC, 150mA (Class 2)
Ballast or Incandescent Load: 20A
Motor Load: 1HP
UL 2043 Plenum Rated
Enclosed Energy Management Equipment: UL 9034


ibis NETWORKS

FC

UL LISTED

WELT
WELT
WELT
WELT





Model: IM-301

Manufacturer:

UL File: E178522

Complies FCC ID: 2ACN300

Input: 120V/170WAC, 50/60Hz

Output: 24VDC, 150mA (Class 2)


Rated or Maximum Load: 20A

Max Load: 500

UL 2043 Penum Listed

Industrial Energy Management Equipment: UL 9034

Ibis NETWORKS



Model: IM-301
IntelliMeter

UL File: E470522

Contains FCC ID: 2AECN300

Input: 120-277VAC, 50/60Hz

Output: 24VDC, 150mA (Class 2)

Ballast or Incandescent Load: 20A

Motor Load: 1HP

UL 2043 Plenum Rated

Enclosed Energy Management Equipment: UL 9034



Ibis NETWORKS



BLK (Line)

WHT (Neutral)

RED (Load)



RED (24VDC)

BLK (Common)

BLU (Occupancy)

ORG (Switch)



Energy Management Equipment
E470522



ibis NETWORKS

IntelliMeter

Model: IM-303

Contains FCC ID: 2AECN300
120-277V 30A 50/60Hz 40C
For indoor use only

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.





