

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124


Worst Case Position

Below 1GHz:	Horizontal: X-axis /	Vertical: X-axis
Above 1 GHz:	Horizontal: Z-axis /	Vertical: Y-axis
Bandedge:	Horizontal: Y-axis /	Vertical: Z-axis


X-axis



Y-axis



Z-axis



End of Report