



INTERTEK TESTING SERVICE

Report No.: 15031369HKG-001

Equipment Photographs

Model: MP3441

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15031369HKG-001

Equipment Photographs

Model: MP3441

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15031369HKG-001

Equipment Photographs

Model: MP3441

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15031369HKG-001

Equipment Photographs

Model: MP3441

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15031369HKG-001

Equipment Photographs

Model: MP3441

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15031369HKG-001

Equipment Photographs

Model: MP3441

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15031369HKG-001

Equipment Photographs

Model: MP3441

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15031369HKG-001

Equipment Photographs

Model: MP3441

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15031369HKG-001

Equipment Photographs

Model: MP3441

(Internal)

