



Southwire®

September 10, 2015

Federal Communications Commission
Equipment Authorization Branch 7435
Oakland Mills Road Columbia, MD
21046

Re: Part 2.933 Change in Identification to FCC ID: 2AENI-M900P

Dear Sir or Madam:

I hereby request a change in identification in accordance to CFR 47 Part 2.933 of the FCC rules. The original identification used on the equipment prior to this application for Change in Identification is HSW-DNT900. The date of the original grant of the equipment authorization 12/31/2008.

I certify that the equipment bearing the modified identification, FCC ID: 2AENI-M900P, does not differ from the original equipment.

I further certify that the original test results continue to be representative of and applicable to the equipment bearing the changed identification.

If you have any questions, please contact Cheryl D. White via phone 1-770-832-5039 or email at cheryl.white@southwire.com.

Sincerely,

Cheryl D. White
Manager Certifications
Southwire Co
One Southwire Drive
Carrollton, GA 30119