

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 220
2AEP2-THAWK1
17-0097
June 13, 2017
Headsight, Inc.
HT5200

Internal Photographs



Figure 1. Lid Removed

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 220
2AEP2-THAWK1
17-0097
June 13, 2017
Headsight, Inc.
HT5200




Figure 2. Internal Components View 1

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 220
2AEP2-THAWK1
17-0097
June 13, 2017
Headsight, Inc.
HT5200




Figure 3. Internal Components View 2

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 220
2AEP2-THAWK1
17-0097
June 13, 2017
Headsight, Inc.
HT5200




Figure 4. Component Side of PCB

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 220
2AEP2-THAWK1
17-0097
June 13, 2017
Headsight, Inc.
HT5200



Figure 5. Solder Side of PCB

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 220
2AEP2-THAWK1
17-0097
June 13, 2017
Headsight, Inc.
HT5200



Figure 6. Antenna Side 1

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 220
2AEP2-THAWK1
17-0097
June 13, 2017
Headsight, Inc.
HT5200



Figure 7. Antenna Side 2

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 220
2AEP2-THAWK1
17-0097
June 13, 2017
Headsight, Inc.
HT5200



Figure 8. RF Module with Shield Removed