


INTERTEK TESTING SERVICE

Report No.: 16071012HKG-001

Equipment Photographs

Model: SP2320-IR-FGPBBT

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16071012HKG-001

Equipment Photographs

Model: SP2320-IR-FGPBBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16071012HKG-001

Equipment Photographs

Model: SP2320-IR-FGPBBT

(Internal)



FCC ID: 2AFOO-SP2320FPBT

IC: 20851-SP2320FPBT



INTERTEK TESTING SERVICE

Report No.: 16071012HKG-001

Equipment Photographs

Model: SP2320-IR-FGPBBT

(Internal)



FCC ID: 2AFOO-SP2320FPBT

IC: 20851-SP2320FPBT


INTERTEK TESTING SERVICE

Report No.: 16071012HKG-001

Equipment Photographs

Model: SP2320-IR-FGPBBT

(Internal)



FCC ID: 2AFOO-SP2320FPBT
IC: 20851-SP2320FPBT