


INTERTEK TESTING SERVICE

Report No.: 16061720HKG-001

Equipment Photographs

Model: SP2618-HE-FGPBBT

(Internal)



FCC ID: 2AFOO-SP2618FPBT
IC: 20851-SP2618FPBT

Report No.: 16061720HKG-001

Model: SP2618-HE-FGPBBT

[illegible]



INTERTEK TESTING SERVICE

Report No.: 16061720HKG-001

Equipment Photographs

Model: SP2618-HE-FGPBBT

(Internal)



FCC ID: 2AFOO-SP2618FPBT
IC: 20851-SP2618FPBT



INTERTEK TESTING SERVICE

Report No.: 16061720HKG-001

Equipment Photographs

Model: SP2618-HE-FGPBBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16061720HKG-001

Equipment Photographs

Model: SP2618-HE-FGPBBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16061720HKG-001

Equipment Photographs

Model: SP2618-HE-FGPBBT

(Internal)



FCC ID: 2AFOO-SP2618FPBT
IC: 20851-SP2618FPBT

INTERTEK TESTING SERVICE

Report No.: 16061720HKG-001

Equipment Photographs

Model: SP2618-HE-FGPBBT

(Internal)

