

Appendix D. SAR Test Setup Photos

Head Exposure Condition



Face-Worn at 0mm



Rest-on-Head at 0mm

Body-worn Exposure Condition



Back at 0 mm



Front at 5 mm



Top edge at 0° with Clamshell at 5 mm



Top edge at 45° with Clamshell at 5 mm



Top edge at -45° with Clamshell at 5 mm



Bottom edge at 0° with Clamshell at 5 mm



Bottom edge at 45° with Clamshell at 5 mm



Bottom edge at -45° with Clamshell at 5 mm



Front edge with Triangle at 5 mm



Back edge with Triangle at 5 mm



Bottom edge with Triangle at 5 mm

Handheld Exposure Condition



Top edge at 0° with Clamshell at 0 mm



Top edge at 45° with Clamshell at 0 mm



Top edge at -45° with Clamshell at 0 mm




Bottom edge at 0° with Clamshell at 0 mm




Bottom edge at 45° with Clamshell at 0 mm




Bottom edge at -45° with Clamshell at 0 mm



Front edge with Clamshell at 0 mm



Back edge with Clamshell at 0 mm



Left edge with Clamshell at 0 mm




Right edge with Clamshell at 0 mm



Front edge with Triangle at 0 mm



Back edge with Triangle at 0 mm



Left edge with Triangle at 0 mm



Right edge with Triangle at 0 mm




Bottom edge with Triangle at 0 mm

PD Test Setup Photo



Outer Edge, Ant 0, 2mm



Outer Edge, Ant 1, 2mm

Appendix D. Antenna Location

