



Internal Photos Antenna 1 and 2





February 24, 2015

Re: Internal Photos of the 940-0132 Module

FCC ID: 2AGQP-F5500

IC: 20936-F5500

To Whom It May Concern,

Rain Bird Corporation does not have internal photos of the 940-0132 Module, as the modules are manufactured using a SIP (System In Package) process. This process results in the final modules being encapsulated in the packaging material during time of manufacture. Based on this we are unable to provide pictures of the module without the cover.

Sincerely,



A handwritten signature in black ink, appearing to read "Anderson Micu".

ANDERSON MICU
Rain Bird Corporation
9491 Ridgehaven Court
San Diego, CA 92111
(858) 268-2638
amicu@rainbird.com

Rain Bird Corporation

6991 E. Southpoint Road, Tucson, AZ 85756 • Phone (520) 741-6100 • Fax (520) 741-6146

EXTERNAL PHOTOS	
Company Name	Rain Bird Corporation
FCC ID #	2AGQP-F5500
IC #	20936-F5500



<u>EXTERNAL PHOTOS</u>	
Company Name	Rain Bird Corporation
FCC ID #	2AGQP-F5500
IC #	20936-F5500

