


INTERTEK TESTING SERVICE

Report No.: 15100448HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AGSV-0201



IC: 20920-0201

INTERTEK TESTING SERVICE

Report No.: 15100448HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AGSV-0201



IC: 20920-0201

INTERTEK TESTING SERVICE

Report No.: 15100448HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AGSV-0201


IC: 20920-0201

INTERTEK TESTING SERVICE

Report No.: 15100448HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AGSV-0201



IC: 20920-0201

INTERTEK TESTING SERVICE

Report No.: 15100448HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AGSV-0201



IC: 20920-0201

INTERTEK TESTING SERVICE

Report No.: 15100448HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AGSV-0201


IC: 20920-0201

INTERTEK TESTING SERVICE

Report No.: 15100448HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AGSV-0201



IC: 20920-0201

INTERTEK TESTING SERVICE

Report No.: 15100448HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AGSV-0201



IC: 20920-0201

INTERTEK TESTING SERVICE

Report No.: 15100448HKG-001

Equipment Photographs

(Internal)



FCC ID: 2AGSV-0201

IC: 20920-0201

INTERTEK TESTING SERVICE

Report No.: 15100448HKG-001

Equipment Photographs

(Internal)

