


INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-02-OB-01

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-02-OB-01

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-02-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA


INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-02-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA


INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-02-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA



INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-02-OB-01

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-02-OB-01

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-02-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA


INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-02-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA



INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-02-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA


INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-02-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA



INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-02-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA

INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-02-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA

INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-04-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA

INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-04-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA


INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-04-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA



INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-04-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA



INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-04-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA


INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-04-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA



INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-04-OB-01

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-04-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA


INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-04-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA



INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-04-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA



INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-04-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA



INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-04-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA

INTERTEK TESTING SERVICE

Report No.: 15120965HKG-001

Equipment Photographs

Model : 4IE-04-OB-01

(Internal)



FCC ID: 2AHBW4IENA

IC: 21121-4IENA