

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.247/ RSS 247
2AHFE-3230
21143-3230
24-0190
August 4, 2025
StreamLabs, Inc
SLRM-3230

EXTERNAL PHOTOGRAPHS




Figure 1. Equipment under Test (Radio module) Frontside

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.247/ RSS 247
2AHFE-3230
21143-3230
24-0190
August 4, 2025
StreamLabs, Inc
SLRM-3230




Figure 2. Equipment under Test (Radio module) Backside

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.247/ RSS 247
2AHFE-3230
21143-3230
24-0190
August 4, 2025
StreamLabs, Inc
SLRM-3230



Figure 3. Front of representative HOST device

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.247/ RSS 247
2AHFE-3230
21143-3230
24-0190
August 4, 2025
StreamLabs, Inc
SLRM-3230




Figure 4. Back of HOST device

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.247/ RSS 247
2AHFE-3230
21143-3230
24-0190
August 4, 2025
StreamLabs, Inc
SLRM-3230



Figure 5. Side (HOST) 1

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.247/ RSS 247
2AHFE-3230
21143-3230
24-0190
August 4, 2025
StreamLabs, Inc
SLRM-3230



Figure 6. Side (HOST) 2

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.247/ RSS 247
2AHFE-3230
21143-3230
24-0190
August 4, 2025
StreamLabs, Inc
SLRM-3230



Figure 7. Side (HOST) 3

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.247/ RSS 247
2AHFE-3230
21143-3230
24-0190
August 4, 2025
StreamLabs, Inc
SLRM-3230



Figure 8. Side (HOST) 4