


CN100

F83



InaPur

InaEn

XT100

PGEC PGED

TX USBQ RTS

GND

MAC-IP

VCC

SCL

MCLR

RX CTS

IntTamper

PORTF4

PORTF5

PORTG6

GDO0

SDA

battMeasEn

HUEn

HULSel

battMeas

MemDetSel

RF1

CS

MISO CLK

MOSI GDO2

rst CC1125

UbattIn

Red Amber

detTamperEn detTamp

hiVoltSirenEn

alarmDetIn

SirenSwitchedGND

HV

Green

ID1-ID0

buttCallPnt_In

VBAT

BkTampPullUp

buttPair

buttSilTst

buttCallP

buttBkTamp

buttBkTamp_In