

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hands Safe Hands, LLC
Gen4 Sensor

EXTERNAL PHOTOGRAPHS



Figure 1. Top of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hands Safe Hands, LLC
Gen4 Sensor



Figure 2. Back of EUT with wall plate

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hands Safe Hands, LLC
Gen4 Sensor




Figure 3. Back of EUT with wall plate removed.
(The EUT is marketed with the wall plate removed.)

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hands Safe Hands, LLC
Gen4 Sensor



Figure 4. Left Side of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hands Safe Hands, LLC
Gen4 Sensor



Figure 5. Right Side of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hands Safe Hands, LLC
Gen4 Sensor




Figure 6. Front of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hands Safe Hands, LLC
Gen4 Sensor



Figure 7. Bottom of EUT