

Model Difference


FCC ID: 2AHS6CX-15D

Model : CX-15D, F87, CX-12D, A15-1, A15-2, PBX-61151, SBX-61151, PBX-61158, DG-1501, PBX-61104, PBX-61120, PBX-61155, BJP-1515BT, PK3000, PKL3500, PK8, PVOLT15BT, PVOLT15, PVOLT12BT, PVOLT12, PVOLT10BT, PVOLT10, PVOLT08BT, PVOLT08, MU-12D, MU-15D, SP6110, DJ-SPIN, DJ15BAT, DJ12BAT, DJ10BAT, DJ8BAT, FT3680, PBS-9922, JBoom8, PBS-9908MP3, PBS-9908MP3BL, PBS-9908MP3RD, PBS-9909MP3, PBS-9909MP3BL, PBS-9909MP3RD, PBS-9910MP3, PBS-9910MP3B, MAHM-6.5AUSBSD, MAHM-12IN2BT, SKL-415, SKL-412, SKL-412M, F22M, F23M, CX-12D, F6-12, F6-15, F12-1, F51, 6814-16, 6827-16, Q7S-16.

The product's different for model number and outlook color.

Regards

Sincerely



Client's signature:

Client's name / title : Buby Zhou / Manager

Contact information / address: Feiyang Industrial Zone, Baiyun District, Guangzhou, China