

LARK ELECTRONICS CO., LTD.

Model Difference

FCC ID: 2AHSIK81

Model : K81


SBX-21000, BT-170, PBX-10700, PBX-10701, PBX-21001,
BT-3165LM, BT-3265LM, BT-3365LM, CS-3025BL, TS-30110, TS-30212D,
TS-31212D, K51, K51A, K51B, K51C, K51D, K6,
K6B, K6C, K6D, K6A, K61, K61A, K61C, K61B, K61D, K18,
K18A, K21, K21A, K81, K82, K6T, K61T, K22, K22A, K1-K3,
K8-K50, K30, A12, A13, A15, A11, A10, A3, A18, A14, A16, A17,
A19, A20, A21, A22, A23, A24, A25, K166, K225, K286, K288,
K212, K288D, K286D, K231A, K231, K212D, K516, K217

All the models are the same circuit and RF module, except the model names and outlook color.

Regards

Sincerely

Client's signature

A handwritten signature in black ink that reads "Sean Liu". The script is cursive and fluid.

Client's name / title : Sean Liu / Manager

Contact information / address: Building B Yushang Industrial Zone, Shiyan, Bao'an, Shenzhen, China