

MODEL : JWM45

CUSTOMER : ASA

DATE : 28/09/2018

DESCRIPTION : LABEL SPECIFICATION

REVISION : 0

PAGE : 1 OF 7

1. Unit label



Blank Label : 602500940G (40x50mm)
Format : Code 128
Position : Unit(1PC)
Remark : 14 digits Barcode

2. GB label



Blank Label : 602500940G (40x50mm)
Format : Code 128
Position : GB(1PC)
Remark : 14 digits Barcode




GB LOGO LABEL: (120x75mm)(2PC)
P/N:908W00000G



WHITE WARNING LABEL(170 x 20mm)(1PC)
FONT SIZE:16PT
P/N: 90AF00010G


3. PDF label



Blank Label : 60-25-00500G (152 x 102mm)
Format : Code 128
Position : Carton(2PC)

2D Barcode: Contained Info of Model No, PO, QTY & First Serial No., last Serial No.
Model No: XXXXX (ASA Model No)
PO: Purchase Order Number.
QTY: Number of units contained in the carton box.
Serial No: Serial No assigned for each unit.


1. MODEL PLATE(80x80mm)
P/N: 508W100A0G





2. Unit label
P/N: 602500940G




3.WARNING LABEL
P/N:908W00010G



4.CLASS 1 LASER PRODUCT LABEL
P/N:90AK00000G




PACKING METHOD



QUICK REFERENCE GUIDE

ACCESSORIES PE BAG

PACKING METHOD (CARTON)



Use the red tape with below letter to seal the master carton as shown.



Figure 1



Figure 2

1. Gift Box Label

 **WARNING:** Cancer and Reproductive Harm-www.p65Warnings.ca.gov

Font Size:16pt



Font Size:12pt Font Size:14pt



220mm



GB P/N:938W20000G

155mm 250mm

2. PDF Label



3. Carton Label P/N: 602500350G



4. Index Label P/N: 6025004A0G



CARTON SPECIFICATION

P/N: 948W10000G

ASA CHICAGO PO : MODEL NO.: C/NO.: MADE IN CHINA	ASA CHICAGO PO : MODEL NO.: C/NO.: MADE IN CHINA	ASA CHICAGO PO : MODEL NO.: C/NO.: MADE IN CHINA	ASA CHICAGO PO : MODEL NO.: C/NO.: MADE IN CHINA

EXTERNAL DIMENSION: 48(L) x26(W) x 24(H)cm

- SPECIFICATION :-
1. MATERIAL : A=A

2. PRINTING : 1 COLOR PROCESS PRINTING - BLACK (FONT : ARIAL)

3. QUALITY : NO DOUBLE IMAGE PRINTING, INK CONSISTENCY & NO OVERLAPING.

4. REMARK : COMPLETED 2 PCS/CTN


5. OTHERS : (A) = BOX CERTIFICATED

PO: TO BE PRINTING ON CARTON (REFER TO MO)


C/NO: USING HANDWRITING (1,2,3....)

6. TOLERANCE : ±3MM

1.UNIT SIX VIEWS



2. 20P POWER HARNESS




MODEL: JWM45
DESCRIPTION: LOADING CAPACITY

CUSTOMER: ASA
REVISION: 0


DATE: 28/09/2018
PAGE: 7 OF: 7

Customer Loading Capacity



Carton Quantity = 10pcs
Carton Dimension (external) = 48(L) x 26(W) x 24(H)cm
N.W = 9.9 LBS/ 4.5 KGS
G.W = 11.2 LBS/ 5.1 KGS


Example:



Pallet size: 1200 x 1000 x 125mm
(48" x 40")


Quantity per layer: 8 cartons
Stacking layer: 5 layers

20' Container Top View




Stacking Layer: 8 Layers

40' Container Top View



Front View



20' Container (without pallets)
Loading Quantity:
= 95 x H8
= 760 cartons x 3 sets
= 2,280 sets

40' Container (without pallets)
Loading Quantity:
= 196 x H8
= 1,568 cartons x 3 sets
= 4,704 sets