

# ***Radio Solutions, Inc.***

55 Accord Park Drive, Norwell, MA 02061 Tel: 781-331-1008 Fax: 781-561-7770

**Subject: External Photos for 2AHVPSB400M2A**



Front View



Bottom View With Antenna Ports and Cutouts for Power and Signalling Connections



Top View



Right Side



Left Side



Back View

**Part 90 Signal Boosters**

**THIS IS A 90.219 CLASS B DEVICE**

WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Class B signal boosters (as defined in 47 CFR 90.219) online at [www.fcc.gov/signal-boosters/registration](http://www.fcc.gov/signal-boosters/registration). Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference, and
- (2) This device must accept any interference received, that may cause undesired operation.



Label Samples

