



Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046
USA

Date: 5/4/2023

Re: Attestation

FCC ID: 2AHVPSB7800M5BDSP, 2AHVPSB7800M5BANA, 2AHVPSB7800M5ADSP, 2AHVPSB800M5BDSP,
2AHVPSB800M5BANA, 2AHVPSB800M5ADSP, 2AHVPSB700M5BDSP, 2AHVPSB700M5BANA,
2AHVPSB700M5ADSP

This equipment meets the requirements of the FCC Rules, Part 90.203(e) and (g), as applicable.

Programming of this product's transmit frequencies can be performed ONLY by the manufacturer or by service or maintenance personnel. The operator cannot program transmit frequencies using the equipment's external operation controls.

Sincerely,

Admir Surkovic

CEO, CTO

admir@radiosolutionsinc.com

Direct: +1-781-561-0707

A handwritten signature in blue ink, appearing to read "Admir", is written over the printed name and email address.