






3 Internal Photos of the EUT





Shenzhen Asia Test Technology Co., Ltd.



Report No. ATT-2016SZ0516846
- Page 10 of 24 -





Shenzhen Asia Test Technology Co., Ltd.

Report No. ATT-2016SZ0516846
- Page 11 of 24 -





Shenzhen Asia Test Technology Co., Ltd.



Report No. ATT-2016SZ0516846
- Page 12 of 24 -





Shenzhen Asia Test Technology Co., Ltd.


Report No. ATT-2016SZ0516846
- Page 13 of 24 -





Shenzhen Asia Test Technology Co., Ltd.



Report No. ATT-2016SZ0516846
- Page 14 of 24 -





Shenzhen Asia Test Technology Co., Ltd.


Report No. ATT-2016SZ0516846
- Page 15 of 24 -





Shenzhen Asia Test Technology Co., Ltd.


Report No. ATT-2016SZ0516846
- Page 16 of 24 -





Shenzhen Asia Test Technology Co., Ltd.

Report No. ATT-2016SZ0516846
- Page 17 of 24 -





Shenzhen Asia Test Technology Co., Ltd.


Report No. ATT-2016SZ0516846
- Page 18 of 24 -





Shenzhen Asia Test Technology Co., Ltd.


Report No. ATT-2016SZ0516846
- Page 19 of 24 -





Shenzhen Asia Test Technology Co., Ltd.

Report No. ATT-2016SZ0516846
- Page 20 of 24 -





Shenzhen Asia Test Technology Co., Ltd.


Report No. ATT-2016SZ0516846
- Page 21 of 24 -





Shenzhen Asia Test Technology Co., Ltd.


Report No. ATT-2016SZ0516846
- Page 22 of 24 -





Shenzhen Asia Test Technology Co., Ltd.

Report No. ATT-2016SZ0516846
- Page 23 of 24 -





Shenzhen Asia Test Technology Co., Ltd.

Report No. ATT-2016SZ0516846
- Page 24 of 24 -

