

APPENDIX 3: Photographs of test setup

Conducted Emission

(Antenna : M/N 146153)




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Conducted Emission
(Antenna : M/N H2U84W1H1S)




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission
(Antenna : M/N 146153)




Photo 1




Photo 2

Worst Case Position


(Antenna : M/N 146153)

(Antenna)


Above 1GHz (Horizontal: X-axis / Vertical: Y-axis)

Above 18GHz and Below 1GHz (Horizontal: X-axi / Vertical: X-axis)


X-axis



Y-axis



Z-axis



Worst Case Position

(Antenna : M/N 146153)


(Module)

(Horizontal: X-axis/ Vertical:X-axis)


X-axis



Y-axis



Z-axis



Radiated Spurious Emission
(Antenna : M/N H2U84W1H1S)




Photo 1




Photo 2

Worst Case Position
(Antenna : M/N H2U84W1H1S)

(Antenna and Module)


Above 1GHz (Horizontal: X-axis/ Vertical:X-axis)

Below 1GHz (Horizontal: X-axis/ Vertical:X-axis)


X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124