




n38_30MHz_30kHz_2585MHz_DFT-s-OFDM QPSK_RB1@0
-36.37dBm




n38_30MHz_30kHz_2585MHz_DFT-s-OFDM QPSK_RB1@77
-36.88dBm




n38_30MHz_30kHz_2585MHz_DFT-s-OFDM QPSK_RB75@0
-35.81dBm




n38_30MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@0
-36.17dBm




n38_30MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@77
-36.68dBm




n38_30MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB75@0
-36.66dBm




n38_30MHz_30kHz_2605MHz_DFT-s-OFDM QPSK_RB1@0
-36.86dBm




n38_30MHz_30kHz_2605MHz_DFT-s-OFDM QPSK_RB1@77
-35.60dBm




n38_30MHz_30kHz_2605MHz_DFT-s-OFDM QPSK_RB75@0
-36.79dBm




n38_40MHz_30kHz_2590MHz_DFT-s-OFDM QPSK_RB1@0
-36.05dBm




n38_40MHz_30kHz_2590MHz_DFT-s-OFDM QPSK_RB1@105
-36.29dBm




n38_40MHz_30kHz_2590MHz_DFT-s-OFDM QPSK_RB100@0
-36.59dBm




n38_40MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@0
-36.73dBm




n38_40MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@105
-36.81dBm




n38_40MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB100@0
-36.16dBm




n38_40MHz_30kHz_2600MHz_DFT-s-OFDM QPSK_RB1@0
-36.15dBm



n38_40MHz_30kHz_2600MHz_DFT-s-OFDM QPSK_RB1@105
-35.93dBm




n38_40MHz_30kHz_2600MHz_DFT-s-OFDM QPSK_RB100@0
-36.21dBm




n41

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM QPSK_RB1@0
-36.97dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:19:56

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB1@23 -36.83dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:20:47

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB24@0 -36.54dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:21:37

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0
-36.46dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:23:01

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@23 -36.81dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:23:42

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB24@0 -36.79dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:24:24


n41_10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB1@0
-36.32dBm




n41_10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB1@23
-36.69dBm




n41_10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB24@0
-36.82dBm




n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@0
-36.32dBm




n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@37
-36.47dBm



n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB36@0
-36.22dBm




n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0
-36.94dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:31:09

n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@37 -36.67dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:31:48

n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB36@0 -36.75dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:32:29

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM QPSK_RB1@0
-36.47dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 16.MAY.2025 23:10:00

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB1@37 -36.79dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:34:36

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB36@0 -36.67dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:35:17

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM QPSK_RB1@0
-36.48dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:36:34

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB1@50 -36.57dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:37:15

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB50@0 -36.41dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:37:56

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0
-36.90dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:38:38

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@50 -36.94dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 16.MAY.2025 23:10:40

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB50@0 -36.44dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:41:01

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@0
-36.09dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:42:26

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@50 -36.78dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:43:09

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB50@0 -36.42dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:44:01

n41_30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB1@0
-37dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 16.MAY.2025 23:11:18

n41_30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB1@77
-36.55dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:45:49

n41_30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB75@0
-36.25dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:46:31

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0
-36.73dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:47:58

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@77 -36.89dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:48:40

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB75@0 -36.83dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:49:32

n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM QPSK_RB1@0
-35.94dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:50:59

n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM
QPSK_RB1@77 -36.61dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:51:40

n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM
QPSK_RB75@0 -36.17dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:52:31

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@0
-36.47dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:53:46

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB1@105 -36.68dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:55:16

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB100@0 -36.43dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:55:58

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0
-36.37dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:57:26

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@105 -36.84dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:58:08

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB100@0 -36.50dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 03:59:00


n41_40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB1@0
-37.07dBm




n41_40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB1@105
-36.49dBm




n41_40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB100@0
-36.56dBm




n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM QPSK_RB1@0
-36.66dBm




n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB1@132 -36.77dBm



n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB128@0 -36.66dBm




n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0
-36.88dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 08:22:54

n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@132 -36.83dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 08:23:29

n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB128@0 -36.33dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 08:24:04

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@0
-36.80dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:13:26

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@132 -36.99dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:14:09

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB128@0 -36.48dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:15:01


n41_60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB1@0
-37.05dBm




n41_60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB1@161
-36.70dBm




n41_60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB162@0
-36.78dBm




n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0
-36.49dBm




n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@161 -36.80dBm



n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB162@0 -36.74dBm




n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM QPSK_RB1@0
-36.61dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:22:04

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB1@161 -36.41dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:22:45

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB162@0 -36.64dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:23:50

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM QPSK_RB1@0
-36.47dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:25:18

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB1@216 -36.95dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 16.MAY.2025 23:11:55

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB216@0 -36.60dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:26:41

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0
-36.74dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:28:11

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@216 -36.37dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:28:54

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB216@0 -36.92dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:29:47

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM QPSK_RB1@0
-36.59dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:31:16

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB1@216 -35.77dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:31:59

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB216@0 -36.69dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:32:41


n41_90MHz_30kHz_2541MHz_DFT-s-OFDM QPSK_RB1@0
-36.79dBm




n41_90MHz_30kHz_2541MHz_DFT-s-OFDM QPSK_RB1@244
-36.86dBm




n41_90MHz_30kHz_2541MHz_DFT-s-OFDM QPSK_RB243@0
-36.71dBm




n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0
-37dBm




n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@244 -36.75dBm



n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB243@0 -36.89dBm




n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM QPSK_RB1@0
-36.93dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:39:27

n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM QPSK_RB1@244 -36.60dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:40:09

n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM QPSK_RB243@0 -36.51dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:40:50

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM QPSK_RB1@0 -36.96dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:41:55

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM QPSK_RB1@272 -36.50dBm



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:42:39

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM QPSK_RB270@0 -36.71dBm



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 7.MAY.2025 04:43:22