



n77_3_15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0
-34.63dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:41:22

n77_3_15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@37
-34.10dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:42:06

n77_3_15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB36@0
-34.61dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:42:51

n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@0 -33.90dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:43:38

n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@37 -34.64dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:44:22

n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB36@0 -34.76dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:45:07

n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB1@0
-34.62dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:45:56

n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB1@50
-34.49dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:47:00

n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB50@0
-34.14dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:47:45

n77_3_20MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0
-34.65dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:48:33

n77_3_20MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@50
-34.83dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:49:18

n77_3_20MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB50@0
-34.73dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:50:03

n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB1@0
-34.74dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:50:51

n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB1@50
-34.57dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:51:38

n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB50@0
-34.78dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:52:24

n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0
-34.38dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:53:18

n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@77
-34.39dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:54:04

n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB75@0
-34.74dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:54:49

n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0
-34.12dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:55:38

n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@77
-34.57dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:56:24

n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB75@0
-34.32dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:57:10

n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM QPSK_RB1@0
-34.41dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:57:58

n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM QPSK_RB1@77
-34.62dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:58:44

n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM QPSK_RB75@0
-34.63dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 20:59:30

n77_3_40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0
-34.01dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:00:20

n77_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@105 -34.90dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:01:06

n77_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0 -34.03dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:01:52

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0
-34.55dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:02:48

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@105 -34.23dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:03:34

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB100@0 -34.47dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:04:20

n77_3_40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB1@0
-34.43dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:05:16

n77_3_40MHz_30kHz_3960MHz_DFT-s-OFDM
QPSK_RB1@105 -34.60dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:06:02

n77_3_40MHz_30kHz_3960MHz_DFT-s-OFDM
QPSK_RB100@0 -34.73dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:06:47

n77_3_50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0
-34.85dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:07:42

n77_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@132 -34.84dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:08:29

n77_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0 -34.61dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:09:15

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0
-34.41dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:10:04

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@132 -34.54dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:10:50

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB128@0 -34.35dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:11:35

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB1@0
-34.29dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:12:24

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB1@132 -34.52dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:13:09

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB128@0 -33.28dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:13:54


n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0
-34.40dBm




n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@161 -33.72dBm




n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB162@0 -34.48dBm




n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0
-34.72dBm




n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@161 -34.31dBm



n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB162@0 -34.55dBm




n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM QPSK_RB1@0
-34.73dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:22:08

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB1@161 -34.37dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:22:53

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB162@0 -34.39dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:23:38

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0
-34.72dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:24:28

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@188 -34.80dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:25:13

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB180@0 -34.99dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:25:59

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0
-34.42dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:26:46

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@188 -34.76dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:27:32

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB180@0 -34.66dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:28:17

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM QPSK_RB1@0
-34.20dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:29:06

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB1@188 -34.56dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:29:52

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB180@0 -34.61dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:30:38


n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@0
-34.64dBm




n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@216 -34.02dBm




n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0 -34.39dBm




n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0
-34.61dBm




n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@216 -34.54dBm




n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB216@0 -34.73dBm




n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB1@0
-33.95dBm




n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB1@216 -34.72dBm




n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB216@0 -34.07dBm




n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB1@0
-34.42dBm




n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@244 -34.03dBm



n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0 -34.86dBm




n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0
-33.38dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:41:46

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@244 -33.65dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:42:32

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB243@0 -34.30dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:43:21

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB1@0
-34.48dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:44:17

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB1@244 -34.37dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:45:11

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB243@0 -34.42dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:46:03


n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0
-34.36dBm




n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@272 -34.84dBm




n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB270@0 -34.89dBm




n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0
-34.48dBm




n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@272 -34.24dBm




n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB270@0 -34.60dBm



n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB1@0
-34.37dBm




n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB1@272 -34.82dBm




n78_1


n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB270@0 -34.72dBm




n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@0
-38.34dBm




n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@23
-38.59dBm



n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB24@0
-38.50dBm




n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.65dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:57:10

n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@23
-38.77dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:57:55

n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB24@0
-38.57dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:58:40

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@0
-38.56dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 21:59:28

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@23
-38.93dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:00:14

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB24@0
-38.51dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:00:58

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.65dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:01:48

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@37 -38.58dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:02:33

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 -38.78dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:03:18

n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.16dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:04:06

n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@37 -38.73dBm n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB36@0 -38.75dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:04:52




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:05:37


n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.41dBm




n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37 -39.01dBm




n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 -38.90dBm



n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB1@0
-38.44dBm



n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB1@50
-38.72dBm



n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB50@0
-38.25dBm

