



B41_2506MHz_Low_20M_1@0_QPSK
B41_2525.8MHz_Low_20M_1@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 23:43:32

B41_2506MHz_Low_20M_100@0_QPSK
B41_2525.8MHz_Low_20M_100@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 22.MAY.2025 23:05:50

B41_2506MHz_Low_20M_1@0_16QAM
B41_2525.8MHz_Low_20M_1@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 23:43:53

B41_2506MHz_Low_20M_100@0_16QAM
B41_2525.8MHz_Low_20M_100@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 22.MAY.2025 23:06:06

B41_2660.2MHz_High_20M_1@99_QPSK
B41_2680MHz_High_20M_1@99_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 21.MAY.2025 00:08:37


B41_2660.2MHz_High_20M_100@0_QPSK
B41_2680MHz_High_20M_100@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 21.MAY.2025 00:09:59

B41_2660.2MHz_High_20M_1@99_16QAM


B41_2680MHz_High_20M_1@99_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 21.MAY.2025 00:09:02

B41_2660.2MHz_High_20M_100@0_16QAM

B41_2680MHz_High_20M_100@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 21.MAY.2025 00:10:24


LTE CA_66C , Normal

B66_1715.3MHz_Low_10M_1@0_QPSK

B66_1727.3MHz_Low_15M_1@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:04:23




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:05:23

B66_1715.3MHz_Low_10M_1@0_16QAM

B66_1727.3MHz_Low_15M_1@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:04:40



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:05:41

B66_1760.5MHz_High_10M_1@49_QPSK


B66_1772.5MHz_High_15M_1@74_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:37:16

B66_1760.5MHz_High_10M_50@0_QPSK


B66_1772.5MHz_High_15M_75@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 22.MAY.2025 22:20:22

B66_1760.5MHz_High_10M_1@49_16QAM


B66_1772.5MHz_High_15M_1@74_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:37:31

B66_1760.5MHz_High_10M_50@0_16QAM


B66_1772.5MHz_High_15M_75@0_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 22.MAY.2025 22:20:36

B66_1717.5MHz_Low_15M_1@0_QPSK


B66_1729.5MHz_Low_10M_1@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:06:20


B66_1717.5MHz_Low_15M_75@0_QPSK

B66_1729.5MHz_Low_10M_50@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:07:36

B66_1717.5MHz_Low_15M_1@0_16QAM
B66_1729.5MHz_Low_10M_1@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:06:41

B66_1717.5MHz_Low_15M_75@0_16QAM
B66_1729.5MHz_Low_10M_50@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:09:52

B66_1762.7MHz_High_15M_1@74_QPSK
B66_1774.7MHz_High_10M_1@49_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:39:04

B66_1762.7MHz_High_15M_75@0_QPSK
B66_1774.7MHz_High_10M_50@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:39:56

B66_1762.7MHz_High_15M_1@74_16QAM
B66_1774.7MHz_High_10M_1@49_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:39:19

B66_1762.7MHz_High_15M_75@0_16QAM
B66_1774.7MHz_High_10M_50@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:41:58

B66_1713.3MHz_Low_5M_1@0_QPSK
B66_1725MHz_Low_20M_1@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:33:34

B66_1713.3MHz_Low_5M_25@0_QPSK
B66_1725MHz_Low_20M_100@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:34:32

B66_1713.3MHz_Low_5M_1@0_16QAM
B66_1725MHz_Low_20M_1@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:33:50




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:34:50

B66_1758.3MHz_High_5M_1@24_QPSK
B66_1770MHz_High_20M_1@99_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:56:18


B66_1758.3MHz_High_5M_25@0_QPSK
B66_1770MHz_High_20M_100@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:57:32

B66_1758.3MHz_High_5M_1@24_16QAM


B66_1770MHz_High_20M_1@99_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:56:36

B66_1758.3MHz_High_5M_25@0_16QAM


B66_1770MHz_High_20M_100@0_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:57:49

B66_1720MHz_Low_20M_1@0_QPSK


B66_1731.1MHz_Low_5M_1@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:31:46

B66_1720MHz_Low_20M_100@0_QPSK


B66_1731.1MHz_Low_5M_25@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:32:43

B66_1720MHz_Low_20M_1@0_16QAM


B66_1731.1MHz_Low_5M_1@0_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:32:02

B66_1720MHz_Low_20M_100@0_16QAM


B66_1731.1MHz_Low_5M_25@0_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:32:58

B66_1765MHz_High_20M_1@99_QPSK


B66_1776.7MHz_High_5M_1@24_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:54:04

B66_1765MHz_High_20M_100@0_QPSK


B66_1776.7MHz_High_5M_25@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:55:17

B66_1765MHz_High_20M_1@99_16QAM


B66_1776.7MHz_High_5M_1@24_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:54:21

B66_1765MHz_High_20M_100@0_16QAM


B66_1776.7MHz_High_5M_25@0_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:55:38

B66_1715.5MHz_Low_10M_1@0_QPSK


B66_1729.9MHz_Low_20M_1@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:10:29


B66_1715.5MHz_Low_10M_50@0_QPSK

B66_1729.9MHz_Low_20M_100@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:11:23

B66_1715.5MHz_Low_10M_1@0_16QAM
B66_1729.9MHz_Low_20M_1@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:10:44

B66_1715.5MHz_Low_10M_50@0_16QAM
B66_1729.9MHz_Low_20M_100@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:11:41

B66_1755.6MHz_High_10M_1@49_QPSK
B66_1770MHz_High_20M_1@99_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:42:35

B66_1755.6MHz_High_10M_50@0_QPSK
B66_1770MHz_High_20M_100@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:43:28

B66_1755.6MHz_High_10M_1@49_16QAM
B66_1770MHz_High_20M_1@99_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:42:50

B66_1755.6MHz_High_10M_50@0_16QAM
B66_1770MHz_High_20M_100@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:43:43

B66_1720MHz_Low_20M_1@0_QPSK
B66_1734.4MHz_Low_10M_1@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:12:22

B66_1720MHz_Low_20M_100@0_QPSK
B66_1734.4MHz_Low_10M_50@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:13:21

B66_1720MHz_Low_20M_1@0_16QAM
B66_1734.4MHz_Low_10M_1@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:12:40




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:13:40

B66_1760.1MHz_High_20M_1@99_QPSK
B66_1774.5MHz_High_10M_1@49_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:44:20


B66_1760.1MHz_High_20M_100@0_QPSK
B66_1774.5MHz_High_10M_50@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:45:18

B66_1760.1MHz_High_20M_1@99_16QAM


B66_1774.5MHz_High_10M_1@49_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:44:36

B66_1760.1MHz_High_20M_100@0_16QAM


B66_1774.5MHz_High_10M_50@0_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:47:30

B66_1717.5MHz_Low_15M_1@0_QPSK


B66_1732.5MHz_Low_15M_1@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:14:20

B66_1717.5MHz_Low_15M_75@0_QPSK


B66_1732.5MHz_Low_15M_75@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:18:37

B66_1717.5MHz_Low_15M_1@0_16QAM


B66_1732.5MHz_Low_15M_1@0_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:14:38

B66_1717.5MHz_Low_15M_75@0_16QAM


B66_1732.5MHz_Low_15M_75@0_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:18:56

B66_1757.5MHz_High_15M_1@74_QPSK


B66_1772.5MHz_High_15M_1@74_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:48:09

B66_1757.5MHz_High_15M_75@0_QPSK


B66_1772.5MHz_High_15M_75@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:49:08

B66_1757.5MHz_High_15M_1@74_16QAM


B66_1772.5MHz_High_15M_1@74_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:48:26

B66_1757.5MHz_High_15M_75@0_16QAM


B66_1772.5MHz_High_15M_75@0_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:49:24

B66_1717.8MHz_Low_15M_1@0_QPSK


B66_1734.9MHz_Low_20M_1@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:19:35


B66_1717.8MHz_Low_15M_75@0_QPSK

B66_1734.9MHz_Low_20M_100@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:20:50

B66_1717.8MHz_Low_15M_1@0_16QAM
B66_1734.9MHz_Low_20M_1@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:19:54

B66_1717.8MHz_Low_15M_75@0_16QAM
B66_1734.9MHz_Low_20M_100@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:29:14

B66_1752.9MHz_High_15M_1@74_QPSK
B66_1770MHz_High_20M_1@99_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:50:04

B66_1752.9MHz_High_15M_75@0_QPSK
B66_1770MHz_High_20M_100@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:51:07

B66_1752.9MHz_High_15M_1@74_16QAM
B66_1770MHz_High_20M_1@99_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:50:21

B66_1752.9MHz_High_15M_75@0_16QAM
B66_1770MHz_High_20M_100@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:51:23

B66_1720MHz_Low_20M_1@0_QPSK
B66_1737.1MHz_Low_15M_1@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:29:53

B66_1720MHz_Low_20M_100@0_QPSK
B66_1737.1MHz_Low_15M_75@0_QPSK




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:30:50

B66_1720MHz_Low_20M_1@0_16QAM
B66_1737.1MHz_Low_15M_1@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:30:08

B66_1720MHz_Low_20M_100@0_16QAM
B66_1737.1MHz_Low_15M_75@0_16QAM




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:31:05

B66_1755.1MHz_High_20M_1@99_QPSK
B66_1772.2MHz_High_15M_1@74_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:52:01


B66_1755.1MHz_High_20M_100@0_QPSK
B66_1772.2MHz_High_15M_75@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:53:09

B66_1755.1MHz_High_20M_1@99_16QAM


B66_1772.2MHz_High_15M_1@74_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:52:17

B66_1755.1MHz_High_20M_100@0_16QAM


B66_1772.2MHz_High_15M_75@0_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:53:26

B66_1720MHz_Low_20M_1@0_QPSK


B66_1739.8MHz_Low_20M_1@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:35:27

B66_1720MHz_Low_20M_100@0_QPSK


B66_1739.8MHz_Low_20M_100@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 22.MAY.2025 22:19:31

B66_1720MHz_Low_20M_1@0_16QAM


B66_1739.8MHz_Low_20M_1@0_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:35:43

B66_1720MHz_Low_20M_100@0_16QAM


B66_1739.8MHz_Low_20M_100@0_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 22.MAY.2025 22:19:47

B66_1750.2MHz_High_20M_1@99_QPSK


B66_1770MHz_High_20M_1@99_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:58:29

B66_1750.2MHz_High_20M_100@0_QPSK


B66_1770MHz_High_20M_100@0_QPSK



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:59:47

B66_1750.2MHz_High_20M_1@99_16QAM


B66_1770MHz_High_20M_1@99_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 22:58:46

B66_1750.2MHz_High_20M_100@0_16QAM

B66_1770MHz_High_20M_100@0_16QAM



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 20.MAY.2025 23:01:26

***** END *****