




n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM QPSK_RB1@0
-46.88dBm




n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM QPSK_RB1@77
-46.54dBm




n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM QPSK_RB75@0
-46.82dBm




n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-46.72dBm




n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@77
-46.76dBm




n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB75@0
-46.97dBm




n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM QPSK_RB1@0
-46.73dBm




n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM QPSK_RB1@77
-46.65dBm




n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM QPSK_RB75@0
-46.84dBm




n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM QPSK_RB1@0
-46.65dBm




n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB1@105 -46.77dBm



n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB100@0 -46.89dBm




n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-46.73dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:42:21

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@105 -46.94dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:43:09

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB100@0 -46.63dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:43:56

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM QPSK_RB1@0
-46.01dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:44:47

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB1@105 -46.45dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:45:33

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB100@0 -46.75dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:46:26

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM QPSK_RB1@0
-46.65dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:47:16

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB1@132 -46.33dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:48:03

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB128@0 -46.87dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:48:51

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-46.59dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:49:40

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@132 -46.06dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:50:27

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB128@0 -46.82dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:51:13


n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM QPSK_RB1@0
-46.55dBm




n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB1@132 -46.55dBm




n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB128@0 -46.79dBm




n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM QPSK_RB1@0
-46.81dBm




n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB1@161 -46.64dBm




n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB162@0 -46.92dBm




n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-46.08dBm




n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@161 -46.42dBm




n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB162@0 -46.65dBm




n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM QPSK_RB1@0
-46.54dBm




n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB1@161 -46.56dBm




n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB162@0 -45.98dBm




n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM QPSK_RB1@0
-46.61dBm




n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB1@188 -46.45dBm




n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB180@0 -46.98dBm




n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-46.72dBm




n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@188 -46.29dBm




n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB180@0 -46.20dBm




n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB1@0
-46.67dBm




n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@188 -46.98dBm




n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB180@0 -46.48dBm




n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB1@0
-46.52dBm




n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@216 -46.55dBm




n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB216@0 -46.74dBm




n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-46.79dBm




n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@216 -46.06dBm




n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB216@0 -46.51dBm




n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB1@0
-47.14dBm




n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@216 -47.06dBm



n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB216@0 -46.84dBm




n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB1@0
-46.50dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:16:18

n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@244 -46.96dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:17:05

n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB243@0 -46.46dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:17:51

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-46.68dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:18:39

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@244 -46.88dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:19:26

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB243@0 -46.82dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:20:12

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB1@0
-46.40dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:21:00

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@244 -46.58dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:21:46

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB243@0 -46.77dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:22:33

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB1@0
-46.94dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:23:24

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@272 -46.61dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:24:09

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB270@0 -46.41dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:24:54

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-46.66dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:25:43

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@272 -47.06dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:26:28

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB270@0 -46.63dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:27:15

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB1@0
-45.73dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:28:04

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@272 -46.62dBm



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:28:50

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB270@0 -46.10dBm



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:29:37