



70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB1@0 -52.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:36:06

70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB1@0 -46.45 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:37:08

70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB1@188 -46.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:39:13

70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB1@188 -51.78 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:38:11

70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB180@0 -52.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:40:15

70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB180@0 -42.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:41:12

80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB1@0 -43.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:43:04

80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB1@0 -52.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:42:07

80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB1@216 -52.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:43:57

80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB1@216 -44.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:44:54

80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB216@0 -44.02 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:46:45

80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB216@0 -52.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:45:48

80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -51.77 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:47:37

80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -44.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:48:35

80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@216 -52.27 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:49:29

80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@216 -44.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:50:27

80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB216@0 -52.12 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:51:40

80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB216@0 -43.97 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:52:37

80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB1@0 -45.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:54:27

80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB1@0 -52.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:53:30

80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB1@216 -51.55 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:55:21

80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB1@216 -46.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:56:18

80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB216@0 -43.78 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:47:22

80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB216@0 -52.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:57:11

90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB1@0 -52.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:59:01

90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB1@0 -46.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 07:59:58

90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB1@244 -46.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:01:48

90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB1@244 -50.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:00:50

90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB243@0 -46.67 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:03:38

90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB243@0 -51.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:02:42

90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -46.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:05:30

90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -51.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:04:32

90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@244 -44.14 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:07:20

90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@244 -52.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:06:23

90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB243@0 -46.47 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:09:09

90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB243@0 -52.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:08:13

90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB1@0 -51.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:10:03

90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB1@0 -43.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:11:01

90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB1@244 -52.47 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:11:55

90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB1@244 -43.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:12:52

90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB243@0 -44.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:14:43

90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB243@0 -52.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:13:46

100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB1@0 -43.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:16:35

100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB1@0 -51.78 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:15:38

100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB1@272 -46.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:18:31

100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB1@272 -50.16 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:17:30

100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB270@0 -51.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:19:45

100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB270@0 -45.41 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:20:45

100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -43.90 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:22:50

100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -52.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:21:48

100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@272 -51.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:23:51

100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@272 -44.10 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:24:51

100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB270@0 -51.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:25:53

100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB270@0 -43.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:26:52

100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB1@0 -52.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:27:54

100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB1@0 -44.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:28:55

100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB1@272 -51.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:29:53

100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB1@272 -43.90 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:30:49

100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB270@0 -52.32 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:31:43


100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB270@0 -46.02 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:32:40


n78_2

10MHz_15kHz_3555MHz_DFT-s-OFDM QPSK_RB1@0 -51.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 17:32:52

10MHz_15kHz_3555MHz_DFT-s-OFDM QPSK_RB1@0 -44.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 17:33:47

10MHz_15kHz_3555MHz_DFT-s-OFDM QPSK_RB1@51 -51.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:36:50

10MHz_15kHz_3555MHz_DFT-s-OFDM QPSK_RB1@51 -46.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:37:47

10MHz_15kHz_3555MHz_DFT-s-OFDM QPSK_RB50@0 -44.26 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:57:23

10MHz_15kHz_3555MHz_DFT-s-OFDM QPSK_RB50@0 -46.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:56:51


10MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -51.79 dBm




10MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -43.71 dBm




10MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@51 -52.12 dBm




10MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@51 -44.27 dBm




10MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB50@0 -52.32 dBm



10MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB50@0 -44.13 dBm




10MHz_15kHz_3695MHz_DFT-s-OFDM QPSK_RB1@0 -46.53 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:52:10

10MHz_15kHz_3695MHz_DFT-s-OFDM QPSK_RB1@0 -51.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:51:07

10MHz_15kHz_3695MHz_DFT-s-OFDM QPSK_RB1@51 -51.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:53:17

10MHz_15kHz_3695MHz_DFT-s-OFDM QPSK_RB1@51 -43.76 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:54:17

10MHz_15kHz_3695MHz_DFT-s-OFDM QPSK_RB50@0 -43.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:56:06

10MHz_15kHz_3695MHz_DFT-s-OFDM QPSK_RB50@0 -52.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:55:10

10MHz_30kHz_3555MHz_DFT-s-OFDM QPSK_RB1@0 -46.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:31:07

10MHz_30kHz_3555MHz_DFT-s-OFDM QPSK_RB1@0 -52.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:30:09

10MHz_30kHz_3555MHz_DFT-s-OFDM QPSK_RB1@23 -43.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:33:00

10MHz_30kHz_3555MHz_DFT-s-OFDM QPSK_RB1@23 -52.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:32:03

10MHz_30kHz_3555MHz_DFT-s-OFDM QPSK_RB24@0 -52.31 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:34:29

10MHz_30kHz_3555MHz_DFT-s-OFDM QPSK_RB24@0 -44.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:35:26

10MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -51.91 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:36:45

10MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -44.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:37:43

10MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@23 -51.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:39:01

10MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@23 -44.10 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:39:59

10MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB24@0 -44.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:01:41

10MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB24@0 -52.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:01:09

10MHz_30kHz_3695MHz_DFT-s-OFDM QPSK_RB1@0 -51.66 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 17:51:46

10MHz_30kHz_3695MHz_DFT-s-OFDM QPSK_RB1@0 -46.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 17:52:41

10MHz_30kHz_3695MHz_DFT-s-OFDM QPSK_RB1@23 -50.84 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 17:59:14

10MHz_30kHz_3695MHz_DFT-s-OFDM QPSK_RB1@23 -46.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:06:51

10MHz_30kHz_3695MHz_DFT-s-OFDM QPSK_RB24@0 -44.41 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:09:01

10MHz_30kHz_3695MHz_DFT-s-OFDM QPSK_RB24@0 -52.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:08:06

15MHz_15kHz_3557.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.54 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:58:02

15MHz_15kHz_3557.5MHz_DFT-s-OFDM QPSK_RB1@0 -52.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:57:03

15MHz_15kHz_3557.5MHz_DFT-s-OFDM QPSK_RB1@78 -52.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:58:59

15MHz_15kHz_3557.5MHz_DFT-s-OFDM QPSK_RB1@78 -46.53 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 08:59:58

15MHz_15kHz_3557.5MHz_DFT-s-OFDM QPSK_RB75@0 -52.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:00:57

15MHz_15kHz_3557.5MHz_DFT-s-OFDM QPSK_RB75@0 -43.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:01:56

15MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -43.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:03:55

15MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -52.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:02:56

15MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@78 -43.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:05:51

15MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@78 -51.65 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:04:52

15MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB75@0 -44.42 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:07:46

15MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB75@0 -51.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:06:47

15MHz_15kHz_3692.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.62 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:09:58

15MHz_15kHz_3692.5MHz_DFT-s-OFDM QPSK_RB1@0 -52.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:08:54

15MHz_15kHz_3692.5MHz_DFT-s-OFDM QPSK_RB1@78 -51.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:11:04

15MHz_15kHz_3692.5MHz_DFT-s-OFDM QPSK_RB1@78 -44.12 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:12:08

15MHz_15kHz_3692.5MHz_DFT-s-OFDM QPSK_RB75@0 -43.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:14:17

15MHz_15kHz_3692.5MHz_DFT-s-OFDM QPSK_RB75@0 -52.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:13:16

15MHz_30kHz_3557.5MHz_DFT-s-OFDM QPSK_RB1@0 -51.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:10:18

15MHz_30kHz_3557.5MHz_DFT-s-OFDM QPSK_RB1@0 -43.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:11:14

15MHz_30kHz_3557.5MHz_DFT-s-OFDM QPSK_RB1@37 -52.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:12:07

15MHz_30kHz_3557.5MHz_DFT-s-OFDM QPSK_RB1@37 -44.40 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:13:05

15MHz_30kHz_3557.5MHz_DFT-s-OFDM QPSK_RB36@0 -46.41 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:14:56

15MHz_30kHz_3557.5MHz_DFT-s-OFDM QPSK_RB36@0 -52.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:14:01

15MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -52.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:15:49

15MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -43.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:16:45

15MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@37 -51.84 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:17:36

15MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@37 -46.41 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:18:31

15MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB36@0 -51.69 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:19:24

15MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB36@0 -44.18 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:20:20

15MHz_30kHz_3692.5MHz_DFT-s-OFDM QPSK_RB1@0 -52.16 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:21:30

15MHz_30kHz_3692.5MHz_DFT-s-OFDM QPSK_RB1@0 -44.02 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:22:26

15MHz_30kHz_3692.5MHz_DFT-s-OFDM QPSK_RB1@37 -52.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:23:18

15MHz_30kHz_3692.5MHz_DFT-s-OFDM QPSK_RB1@37 -44.18 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:24:13

15MHz_30kHz_3692.5MHz_DFT-s-OFDM QPSK_RB36@0 -52.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:25:06

15MHz_30kHz_3692.5MHz_DFT-s-OFDM QPSK_RB36@0 -43.92 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:26:02

25MHz_15kHz_3562.5MHz_DFT-s-OFDM QPSK_RB1@0 -51.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:15:28

25MHz_15kHz_3562.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:16:25

25MHz_15kHz_3562.5MHz_DFT-s-OFDM QPSK_RB1@132 -52.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:17:20

25MHz_15kHz_3562.5MHz_DFT-s-OFDM QPSK_RB1@132 -44.26 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:18:18

25MHz_15kHz_3562.5MHz_DFT-s-OFDM QPSK_RB128@0 -52.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:19:14

25MHz_15kHz_3562.5MHz_DFT-s-OFDM QPSK_RB128@0 -46.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:20:11

25MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -52.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:58:15

25MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -44.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:58:47

25MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@132 -44.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:00:13

25MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@132 -52.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:59:40

25MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB128@0 -52.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:28:43

25MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB128@0 -44.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:29:40

25MHz_15kHz_3687.5MHz_DFT-s-OFDM QPSK_RB1@0 -52.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:30:36

25MHz_15kHz_3687.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:31:33

25MHz_15kHz_3687.5MHz_DFT-s-OFDM QPSK_RB1@132 -52.18 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:32:28

25MHz_15kHz_3687.5MHz_DFT-s-OFDM QPSK_RB1@132 -44.37 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:33:25

25MHz_15kHz_3687.5MHz_DFT-s-OFDM QPSK_RB128@0 -44.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:35:18

25MHz_15kHz_3687.5MHz_DFT-s-OFDM QPSK_RB128@0 -51.78 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:34:20

25MHz_30kHz_3562.5MHz_DFT-s-OFDM QPSK_RB1@0 -52.43 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:26:56

25MHz_30kHz_3562.5MHz_DFT-s-OFDM QPSK_RB1@0 -44.06 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:27:52

25MHz_30kHz_3562.5MHz_DFT-s-OFDM QPSK_RB1@64 -42.92 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:29:41

25MHz_30kHz_3562.5MHz_DFT-s-OFDM QPSK_RB1@64 -52.67 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:28:46

25MHz_30kHz_3562.5MHz_DFT-s-OFDM QPSK_RB64@0 -43.90 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:31:30

25MHz_30kHz_3562.5MHz_DFT-s-OFDM QPSK_RB64@0 -52.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:30:34

25MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -46.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:33:18

25MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -51.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:32:22

25MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@64 -52.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:34:10

25MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@64 -44.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:35:06

25MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB64@0 -52.69 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:35:57

25MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB64@0 -46.78 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:36:52

25MHz_30kHz_3687.5MHz_DFT-s-OFDM QPSK_RB1@0 -52.65 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:37:44

25MHz_30kHz_3687.5MHz_DFT-s-OFDM QPSK_RB1@0 -44.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:38:39

25MHz_30kHz_3687.5MHz_DFT-s-OFDM QPSK_RB1@64 -52.30 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:39:31

25MHz_30kHz_3687.5MHz_DFT-s-OFDM QPSK_RB1@64 -44.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:40:27

25MHz_30kHz_3687.5MHz_DFT-s-OFDM QPSK_RB64@0 -52.53 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:41:19

25MHz_30kHz_3687.5MHz_DFT-s-OFDM QPSK_RB64@0 -44.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:49:01

30MHz_15kHz_3565MHz_DFT-s-OFDM QPSK_RB1@0 -50.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:36:32

30MHz_15kHz_3565MHz_DFT-s-OFDM QPSK_RB1@0 -44.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:37:30

30MHz_15kHz_3565MHz_DFT-s-OFDM QPSK_RB1@159 -44.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:39:23

30MHz_15kHz_3565MHz_DFT-s-OFDM QPSK_RB1@159 -52.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:38:25

30MHz_15kHz_3565MHz_DFT-s-OFDM QPSK_RB160@0 -52.01 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:40:37

30MHz_15kHz_3565MHz_DFT-s-OFDM QPSK_RB160@0 -46.59 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:41:34