



30MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -52.92 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:42:29

30MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -46.42 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:43:26

30MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@159 -46.65 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:45:19

30MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@159 -52.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:44:21

30MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB160@0 -51.99 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:46:14

30MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB160@0 -44.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:47:11

30MHz_15kHz_3685MHz_DFT-s-OFDM QPSK_RB1@0 -43.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:49:04

30MHz_15kHz_3685MHz_DFT-s-OFDM QPSK_RB1@0 -51.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:48:07

30MHz_15kHz_3685MHz_DFT-s-OFDM QPSK_RB1@159 -43.74 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:50:59

30MHz_15kHz_3685MHz_DFT-s-OFDM QPSK_RB1@159 -52.47 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:50:02

30MHz_15kHz_3685MHz_DFT-s-OFDM QPSK_RB160@0 -43.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:52:51

30MHz_15kHz_3685MHz_DFT-s-OFDM QPSK_RB160@0 -51.99 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:51:54

30MHz_30kHz_3565MHz_DFT-s-OFDM QPSK_RB1@0 -41.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:44:03

30MHz_30kHz_3565MHz_DFT-s-OFDM QPSK_RB1@0 -52.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:43:07

30MHz_30kHz_3565MHz_DFT-s-OFDM QPSK_RB1@77 -51.41 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:44:54

30MHz_30kHz_3565MHz_DFT-s-OFDM QPSK_RB1@77 -46.74 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:45:50

30MHz_30kHz_3565MHz_DFT-s-OFDM QPSK_RB75@0 -52.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:46:42

30MHz_30kHz_3565MHz_DFT-s-OFDM QPSK_RB75@0 -46.30 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:47:37

30MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -52.53 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:48:32

30MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -44.43 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:49:28

30MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@77 -51.42 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:50:21

30MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@77 -44.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:51:17

30MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB75@0 -42.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:53:05

30MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB75@0 -44.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 18:52:09


30MHz_30kHz_3685MHz_DFT-s-OFDM QPSK_RB1@0 -51.79 dBm




30MHz_30kHz_3685MHz_DFT-s-OFDM QPSK_RB1@0 -46.13 dBm




30MHz_30kHz_3685MHz_DFT-s-OFDM QPSK_RB1@77 -43.79 dBm




30MHz_30kHz_3685MHz_DFT-s-OFDM QPSK_RB1@77 -52.07 dBm




30MHz_30kHz_3685MHz_DFT-s-OFDM QPSK_RB75@0 -46.63 dBm



30MHz_30kHz_3685MHz_DFT-s-OFDM QPSK_RB75@0 -50.14 dBm




40MHz_15kHz_3570MHz_DFT-s-OFDM QPSK_RB1@0 -46.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:54:44

40MHz_15kHz_3570MHz_DFT-s-OFDM QPSK_RB1@0 -51.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:53:47

40MHz_15kHz_3570MHz_DFT-s-OFDM QPSK_RB1@215 -52.18 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:55:40

40MHz_15kHz_3570MHz_DFT-s-OFDM QPSK_RB1@215 -46.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:56:36

40MHz_15kHz_3570MHz_DFT-s-OFDM QPSK_RB216@0 -52.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:57:32

40MHz_15kHz_3570MHz_DFT-s-OFDM QPSK_RB216@0 -43.55 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 09:58:29


40MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -51.69 dBm




40MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -46.77 dBm




40MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@215 -46.02 dBm




40MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@215 -52.02 dBm




40MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB216@0 -43.85 dBm



40MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB216@0 -52.23 dBm




40MHz_15kHz_3680MHz_DFT-s-OFDM QPSK_RB1@0 -51.84 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:05:44

40MHz_15kHz_3680MHz_DFT-s-OFDM QPSK_RB1@0 -46.42 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:06:45

40MHz_15kHz_3680MHz_DFT-s-OFDM QPSK_RB1@215 -44.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:08:49

40MHz_15kHz_3680MHz_DFT-s-OFDM QPSK_RB1@215 -51.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:07:49

40MHz_15kHz_3680MHz_DFT-s-OFDM QPSK_RB216@0 -44.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:10:50

40MHz_15kHz_3680MHz_DFT-s-OFDM QPSK_RB216@0 -52.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:09:51


40MHz_30kHz_3570MHz_DFT-s-OFDM QPSK_RB1@0 -52.38 dBm




40MHz_30kHz_3570MHz_DFT-s-OFDM QPSK_RB1@0 -46.03 dBm




40MHz_30kHz_3570MHz_DFT-s-OFDM QPSK_RB1@105 -51.86 dBm




40MHz_30kHz_3570MHz_DFT-s-OFDM QPSK_RB1@105 -46.55 dBm




40MHz_30kHz_3570MHz_DFT-s-OFDM QPSK_RB100@0 -46.37 dBm



40MHz_30kHz_3570MHz_DFT-s-OFDM QPSK_RB100@0 -52.43 dBm




40MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -52.02 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:16:41

40MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -44.02 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:17:37

40MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@105 -44.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:19:26

40MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@105 -51.62 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:18:30

40MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB100@0 -46.26 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:21:11

40MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB100@0 -51.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:20:16

40MHz_30kHz_3680MHz_DFT-s-OFDM QPSK_RB1@0 -44.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:22:59

40MHz_30kHz_3680MHz_DFT-s-OFDM QPSK_RB1@0 -52.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:22:03

40MHz_30kHz_3680MHz_DFT-s-OFDM QPSK_RB1@105 -46.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:24:47

40MHz_30kHz_3680MHz_DFT-s-OFDM QPSK_RB1@105 -50.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:23:51

40MHz_30kHz_3680MHz_DFT-s-OFDM QPSK_RB100@0 -52.14 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:25:38

40MHz_30kHz_3680MHz_DFT-s-OFDM QPSK_RB100@0 -46.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:26:34


50MHz_15kHz_3575MHz_DFT-s-OFDM QPSK_RB1@0 -52.04 dBm




50MHz_15kHz_3575MHz_DFT-s-OFDM QPSK_RB1@0 -46.01 dBm




50MHz_15kHz_3575MHz_DFT-s-OFDM QPSK_RB1@269 -44.45 dBm




50MHz_15kHz_3575MHz_DFT-s-OFDM QPSK_RB1@269 -52.26 dBm




50MHz_15kHz_3575MHz_DFT-s-OFDM QPSK_RB270@0 -44.32 dBm



50MHz_15kHz_3575MHz_DFT-s-OFDM QPSK_RB270@0 -51.97 dBm




50MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -46.43 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:18:33

50MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -51.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:17:34

50MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@269 -52.41 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:19:30

50MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB1@269 -43.92 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:20:28

50MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB270@0 -46.65 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:22:22

50MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB270@0 -52.38 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:21:25

50MHz_15kHz_3675MHz_DFT-s-OFDM QPSK_RB1@0 -46.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:24:43

50MHz_15kHz_3675MHz_DFT-s-OFDM QPSK_RB1@0 -47.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:23:45

50MHz_15kHz_3675MHz_DFT-s-OFDM QPSK_RB1@269 -52.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:25:39

50MHz_15kHz_3675MHz_DFT-s-OFDM QPSK_RB1@269 -46.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:26:37

50MHz_15kHz_3675MHz_DFT-s-OFDM QPSK_RB270@0 -46.47 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:28:51

50MHz_15kHz_3675MHz_DFT-s-OFDM QPSK_RB270@0 -51.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 10:27:53


50MHz_30kHz_3575MHz_DFT-s-OFDM QPSK_RB1@0 -44.02 dBm




50MHz_30kHz_3575MHz_DFT-s-OFDM QPSK_RB1@0 -51.66 dBm




50MHz_30kHz_3575MHz_DFT-s-OFDM QPSK_RB1@132 -52.48 dBm




50MHz_30kHz_3575MHz_DFT-s-OFDM QPSK_RB1@132 -44.49 dBm




50MHz_30kHz_3575MHz_DFT-s-OFDM QPSK_RB128@0 -52.16 dBm



50MHz_30kHz_3575MHz_DFT-s-OFDM QPSK_RB128@0 -44.13 dBm




50MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -46.40 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:33:46

50MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -43.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:02:34

50MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@132 -44.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:35:18

50MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@132 -43.68 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:34:47

50MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB128@0 -44.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:36:42

50MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB128@0 -52.38 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:36:10

50MHz_30kHz_3675MHz_DFT-s-OFDM QPSK_RB1@0 -51.77 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:37:34

50MHz_30kHz_3675MHz_DFT-s-OFDM QPSK_RB1@0 -44.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:38:07

50MHz_30kHz_3675MHz_DFT-s-OFDM QPSK_RB1@132 -43.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:39:56

50MHz_30kHz_3675MHz_DFT-s-OFDM QPSK_RB1@132 -52.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:38:59

50MHz_30kHz_3675MHz_DFT-s-OFDM QPSK_RB128@0 -44.27 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:41:47

50MHz_30kHz_3675MHz_DFT-s-OFDM QPSK_RB128@0 -52.26 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:40:49

60MHz_30kHz_3580MHz_DFT-s-OFDM QPSK_RB1@0 -51.62 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:42:39

60MHz_30kHz_3580MHz_DFT-s-OFDM QPSK_RB1@0 -44.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:43:35

60MHz_30kHz_3580MHz_DFT-s-OFDM QPSK_RB1@161 -46.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:45:24

60MHz_30kHz_3580MHz_DFT-s-OFDM QPSK_RB1@161 -51.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:44:28

60MHz_30kHz_3580MHz_DFT-s-OFDM QPSK_RB162@0 -44.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:47:12

60MHz_30kHz_3580MHz_DFT-s-OFDM QPSK_RB162@0 -52.37 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 19:46:16


60MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -44.40 dBm




60MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -47.75 dBm




60MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@161 -44.29 dBm




60MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@161 -44.80 dBm




60MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB162@0 -52.62 dBm



60MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB162@0 -42.96 dBm




60MHz_30kHz_3670MHz_DFT-s-OFDM QPSK_RB1@0 -52.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:08:08

60MHz_30kHz_3670MHz_DFT-s-OFDM QPSK_RB1@0 -46.31 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:09:04

60MHz_30kHz_3670MHz_DFT-s-OFDM QPSK_RB1@161 -44.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:10:53

60MHz_30kHz_3670MHz_DFT-s-OFDM QPSK_RB1@161 -52.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:09:57

60MHz_30kHz_3670MHz_DFT-s-OFDM QPSK_RB162@0 -43.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:12:43

60MHz_30kHz_3670MHz_DFT-s-OFDM QPSK_RB162@0 -52.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:11:47

70MHz_30kHz_3585MHz_DFT-s-OFDM QPSK_RB1@0 -46.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:13:37

70MHz_30kHz_3585MHz_DFT-s-OFDM QPSK_RB1@0 -46.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:14:34

70MHz_30kHz_3585MHz_DFT-s-OFDM QPSK_RB1@188 -52.06 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:15:27

70MHz_30kHz_3585MHz_DFT-s-OFDM QPSK_RB1@188 -44.23 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:16:23

70MHz_30kHz_3585MHz_DFT-s-OFDM QPSK_RB180@0 -51.37 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:17:36

70MHz_30kHz_3585MHz_DFT-s-OFDM QPSK_RB180@0 -44.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:18:09


70MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -51.20 dBm




70MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -44.08 dBm




70MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@188 -51.83 dBm




70MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@188 -44.11 dBm




70MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB180@0 -52.44 dBm



70MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB180@0 -45.97 dBm




70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB1@0 -46.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:31:12

70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB1@0 -52.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:30:16

70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB1@188 -44.14 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:33:01

70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB1@188 -52.42 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:32:05

70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB180@0 -51.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:33:54

70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB180@0 -43.90 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:34:50

80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB1@0 -50.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:35:43

80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB1@0 -44.02 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:36:39

80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB1@216 -52.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:37:33

80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB1@216 -43.37 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:38:29

80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB216@0 -48.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:39:22

80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB216@0 -43.91 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:40:18

80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -46.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:42:08

80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -52.54 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:41:11

80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@216 -51.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:43:02

80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@216 -44.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:43:59

80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB216@0 -46.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:51:20

80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB216@0 -52.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:44:53

80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB1@0 -46.52 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:47:40

80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB1@0 -51.64 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:46:43

80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB1@216 -43.27 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:49:29

80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB1@216 -51.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:48:33

80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB216@0 -52.31 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:50:29

80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB216@0 -46.37 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:51:32

90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB1@0 -52.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:52:45

90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB1@0 -44.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:53:50

90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB1@244 -46.73 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:52:55

90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB1@244 -52.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:55:01

90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB243@0 -52.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:57:16

90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB243@0 -44.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:58:20

90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -46.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:00:37

90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -50.51 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 20:59:34

90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@244 -52.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:01:36

90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@244 -44.02 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:02:32

90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB243@0 -43.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:04:22

90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB243@0 -51.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:03:26

90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB1@0 -48.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:05:16

90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB1@0 -43.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:06:13

90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB1@244 -44.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:08:04

90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB1@244 -51.52 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:07:07

90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB243@0 -46.39 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:09:55

90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB243@0 -52.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:08:58

100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB1@0 -44.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:11:45

100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB1@0 -42.47 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:10:48

100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB1@272 -52.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:12:39

100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB1@272 -44.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:13:36

100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB270@0 -51.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:14:29

100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB270@0 -46.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:15:26


100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -51.62 dBm




100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0 -44.08 dBm




100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@272 -44.22 dBm




100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@272 -49.53 dBm




100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB270@0 -46.11 dBm



100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB270@0 -52.51 dBm




100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB1@0 -51.94 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:21:47

100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB1@0 -45.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:22:44

100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB1@272 -43.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:24:33

100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB1@272 -47.77 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:23:37

100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB270@0 -51.83 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:25:26

100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB270@0 -46.12 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 21:26:22