



ax20_5260MHz_RU_106/53_Chain 0 -3.67 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 14:56:19

ax20_5260MHz_RU_106/53_Chain 1 -1.72 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:05:54

ax20_5260MHz_RU_242/61_Chain 0 -8.33 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 14:56:44

ax20_5260MHz_RU_242/61_Chain 1 -7.10 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:06:46

ax20_5280MHz_RU_26/0_Chain 0 4.56 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 7.JUN.2024 14:07:12

ax20_5280MHz_RU_26/0_Chain 1 5.66 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 7.JUN.2024 14:08:43

ax20_5280MHz_RU_52/37_Chain 0 2.24 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 14:57:35

ax20_5280MHz_RU_52/37_Chain 1 2.65 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:08:10

ax20_5280MHz_RU_106/53_Chain 0 -3.57 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 14:57:59

ax20_5280MHz_RU_106/53_Chain 1 -2.46 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:09:06

ax20_5280MHz_RU_242/61_Chain 0 -8.55 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 14:58:22

ax20_5280MHz_RU_242/61_Chain 1 -7.82 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:09:43

ax20_5320MHz_RU_26/8_Chain 0 5.22 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 7.JUN.2024 14:09:33

ax20_5320MHz_RU_26/8_Chain 1 5.60 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 7.JUN.2024 14:12:48

ax20_5320MHz_RU_52/40_Chain 0 1.31 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 14:59:25

ax20_5320MHz_RU_52/40_Chain 1 2.31 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:11:20

ax20_5320MHz_RU_106/54_Chain 0 -2.98 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 14:59:54

ax20_5320MHz_RU_106/54_Chain 1 -2.42 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:11:46

ax20_5320MHz_RU_242/61_Chain 0 -8.40 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:00:23

ax20_5320MHz_RU_242/61_Chain 1 -8.49 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:12:21

ax40_5270MHz_RU_26/0_Chain 0 3.98 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:01:07

ax40_5270MHz_RU_26/0_Chain 1 4.82 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:13:20

ax40_5270MHz_RU_52/37_Chain 0 0.46 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:01:36

ax40_5270MHz_RU_52/37_Chain 1 1.80 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:14:01

ax40_5270MHz_RU_106/53_Chain 0 -4.49 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:02:01

ax40_5270MHz_RU_106/53_Chain 1 -3.94 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:14:37

ax40_5270MHz_RU_242/61_Chain 0 -9.19 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:02:26

ax40_5270MHz_RU_242/61_Chain 1 -8.56 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:15:07

ax40_5270MHz_RU_484/65_Chain 0 -12.34 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:02:54

ax40_5270MHz_RU_484/65_Chain 1 -11.49 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:15:34

ax40_5310MHz_RU_26/17_Chain 0 3.07 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:03:28

ax40_5310MHz_RU_26/17_Chain 1 4.33 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:16:15

ax40_5310MHz_RU_52/44_Chain 0 -0.14 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:03:55

ax40_5310MHz_RU_52/44_Chain 1 0.32 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:16:52

ax40_5310MHz_RU_106/56_Chain 0 -4.34 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:04:26

ax40_5310MHz_RU_106/56_Chain 1 -3.07 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:17:18

ax40_5310MHz_RU_242/62_Chain 0 -9.61 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:05:05

ax40_5310MHz_RU_242/62_Chain 1 -8.45 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:17:52

ax40_5310MHz_RU_484/65_Chain 0 -11.86 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:07:09

ax40_5310MHz_RU_484/65_Chain 1 -11.44 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:18:20

ax80_5290MHz_RU_26/0_Chain 0 3.16 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:08:14

ax80_5290MHz_RU_26/0_Chain 1 3.81 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:20:57

ax80_5290MHz_RU_52/37_Chain 0 -0.42 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:08:42

ax80_5290MHz_RU_52/37_Chain 1 0.24 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:21:47

ax80_5290MHz_RU_106/53_Chain 0 -5.26 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:09:09

ax80_5290MHz_RU_106/53_Chain 1 -3.39 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:22:26

ax80_5290MHz_RU_242/61_Chain 0 -9.62 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:09:36

ax80_5290MHz_RU_242/61_Chain 1 -8.61 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:23:05

ax80_5290MHz_RU_484/65_Chain 0 -12.32 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:10:12

ax80_5290MHz_RU_484/65_Chain 1 -11.26 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:23:47

ax80_5290MHz_RU_996/67_Chain 0 -15.22 dBm



Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:10:40


ax80_5290MHz_RU_996/67_Chain 1 -14.51 dBm



Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:24:28


5.6G

a_5500MHz_Chain 0 5.38 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:11:51

a_5500MHz_Chain 1 6.36 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:36:59


a_5580MHz_Chain 0 5.33 dBm




a_5580MHz_Chain 1 6.09 dBm




a_5700MHz_Chain 0 4.69 dBm




a_5700MHz_Chain 1 5.82 dBm




a_5720MHz_Chain 0 5.68 dBm



a_5720MHz_Chain 1 6.31 dBm




n20_5500MHz_Chain 0 4.34 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:24:04

n20_5500MHz_Chain 1 5.03 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:50:09

n20_5580MHz_Chain 0 3.98 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:24:36

n20_5580MHz_Chain 1 5.07 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:52:01

n20_5700MHz_Chain 0 4.70 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:25:01

n20_5700MHz_Chain 1 5.19 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:53:50

n20_5720MHz_Chain 0 4.57 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:26:54

n20_5720MHz_Chain 1 5.46 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:55:47

n40_5510MHz_Chain 0 1.75 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:27:24

n40_5510MHz_Chain 1 2.96 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:58:04

n40_5550MHz_Chain 0 1.78 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:27:48

n40_5550MHz_Chain 1 2.71 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 16:59:44

n40_5670MHz_Chain 0 2.13 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:28:30

n40_5670MHz_Chain 1 2.67 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 17:01:20

n40_5710MHz_Chain 0 2.18 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:29:00

n40_5710MHz_Chain 1 2.92 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 17:03:02

ac80_5530MHz_Chain 0 -3.58 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:29:52

ac80_5530MHz_Chain 1 -2.64 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 17:05:21

ac80_5610MHz_Chain 0 -3.82 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:30:25

ac80_5610MHz_Chain 1 -3.07 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 17:07:57

ac80_5690MHz_Chain 0 -2.89 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 15:30:54

ac80_5690MHz_Chain 1 -2.08 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 17:09:44

ax20_5500MHz_RU_26/0_Chain 0 4.43 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:22:59

ax20_5500MHz_RU_26/0_Chain 1 5.29 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 18:42:30

ax20_5500MHz_RU_52/37_Chain 0 -0.83 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:40:16

ax20_5500MHz_RU_52/37_Chain 1 0.47 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 18:43:20

ax20_5500MHz_RU_106/53_Chain 0 -5.37 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:40:54

ax20_5500MHz_RU_106/53_Chain 1 -4.05 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 18:43:59

ax20_5500MHz_RU_242/61_Chain 0 -8.38 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:41:18

ax20_5500MHz_RU_242/61_Chain 1 -7.52 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 18:44:45

ax20_5580MHz_RU_26/0_Chain 0 4.26 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:25:38

ax20_5580MHz_RU_26/0_Chain 1 4.62 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 18:45:34

ax20_5580MHz_RU_52/37_Chain 0 -1.61 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:41:52

ax20_5580MHz_RU_52/37_Chain 1 0.04 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 18:46:04

ax20_5580MHz_RU_106/53_Chain 0 -6.23 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:42:39

ax20_5580MHz_RU_106/53_Chain 1 -5.00 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 18:46:44

ax20_5580MHz_RU_242/61_Chain 0 -8.79 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:43:03

ax20_5580MHz_RU_242/61_Chain 1 -8.09 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 18:47:16

ax20_5700MHz_RU_26/8_Chain 0 3.27 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:45:11

ax20_5700MHz_RU_26/8_Chain 1 5.33 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:03:30

ax20_5700MHz_RU_52/40_Chain 0 -1.03 dBm



Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:19:02

ax20_5700MHz_RU_52/40_Chain 1 0.32 dBm



Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:04:03