



15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.65 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:10:17

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:09:22

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@37 -47.27 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:11:12

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@37 -37.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:12:07

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB36@0 -37.84 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:13:57

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB36@0 -47.27 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:13:02

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@0 -38.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:15:48

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:14:52

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@37 -46.64 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:16:43

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@37 -37.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:17:38

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB36@0 -47.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:18:34

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB36@0 -37.84 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:19:29


25MHz_30kHz_3462.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.77 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 04:21:18


25MHz_30kHz_3462.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.52 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 04:20:23


25MHz_30kHz_3462.5MHz_DFT-s-OFDM QPSK_RB1@64 -37.11 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 04:23:09


25MHz_30kHz_3462.5MHz_DFT-s-OFDM QPSK_RB1@64 -46.60 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 04:22:14


25MHz_30kHz_3462.5MHz_DFT-s-OFDM QPSK_RB64@0 -47.60 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 04:24:17


25MHz_30kHz_3462.5MHz_DFT-s-OFDM QPSK_RB64@0 -38.14 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 19.MAY.2024 04:25:12

25MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.76 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:27:02

25MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:26:07

25MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@64 -37.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:28:51

25MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@64 -46.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:27:56

25MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB64@0 -38.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:30:42

25MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB64@0 -47.23 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:29:46


25MHz_30kHz_3537.5MHz_DFT-s-OFDM QPSK_RB1@0 -38.05 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:46:52


25MHz_30kHz_3537.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.35 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:45:58


25MHz_30kHz_3537.5MHz_DFT-s-OFDM QPSK_RB1@64 -37.34 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:48:38


25MHz_30kHz_3537.5MHz_DFT-s-OFDM QPSK_RB1@64 -47.45 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:47:43


25MHz_30kHz_3537.5MHz_DFT-s-OFDM QPSK_RB64@0 -47.05 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:49:29


25MHz_30kHz_3537.5MHz_DFT-s-OFDM QPSK_RB64@0 -38.24 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 10:50:23

30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB1@0 -37.64 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:52:14

30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB1@0 -46.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:51:16

30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB1@77 -41.76 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:53:11

30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB1@77 -38.10 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:54:09

30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB75@0 -47.64 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:55:29

30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB75@0 -37.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:56:26

30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -45.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:57:25

30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.95 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:58:23

30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@77 -37.52 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:00:19

30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@77 -39.45 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:59:21

30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB75@0 -37.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:02:17

30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB75@0 -47.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:01:19

30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB1@0 -42.52 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:04:15

30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB1@0 -37.99 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:05:09

30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB1@77 -46.43 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:06:24

30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB1@77 -38.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:07:18

30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB75@0 -37.27 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:09:03

30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB75@0 -47.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:08:09

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@0 -37.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:10:49

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@0 -43.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:09:55

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@105 -46.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:11:41

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@105 -37.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:12:38

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB100@0 -37.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:14:51

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB100@0 -43.55 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:13:50

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.38 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:15:42

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.30 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:16:36

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@105 -47.38 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:17:28

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@105 -38.14 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:18:22

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB100@0 -46.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:19:14

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB100@0 -38.04 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 11:20:08


40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@0 -37.73 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 11:21:54


40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@0 -45.85 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 11:21:00


40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@105 -37.79 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:00:18


40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@105 -47.00 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 11:59:24


40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB100@0 -46.08 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 11:50:37


40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB100@0 -37.94 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 11:51:32


50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@0 -44.71 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 11:52:23


50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@0 -37.78 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 11:53:17


50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@132 -37.94 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 11:55:04


50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@132 -46.53 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 11:54:08


50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB128@0 -47.25 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:01:47


50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB128@0 -37.73 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:02:41


50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.46 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:03:32


50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.68 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:04:26


50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@132 -37.55 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:06:11


50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@132 -47.04 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:05:16


50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB128@0 -37.74 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:07:56


50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB128@0 -47.33 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 12:07:02

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@0 -47.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:08:47

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@0 -37.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:09:42

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@132 -38.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:11:28

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@132 -46.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:10:33

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB128@0 -37.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:13:13

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB128@0 -47.48 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:12:18


60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@0 -47.32 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:14:03


60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@0 -37.90 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:14:58


60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@161 -37.54 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:16:44


60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@161 -47.55 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:15:49


60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB162@0 -37.93 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:18:29


60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB162@0 -46.32 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:17:35


60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.46 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:19:20


60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.82 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:20:14


60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@161 -47.26 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:21:05


60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@161 -37.75 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:21:59


60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB162@0 -47.10 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:22:50


60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB162@0 -37.59 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 12:23:44

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB1@0 -46.78 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:24:35

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB1@0 -37.67 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:25:29

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB1@161 -37.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:27:16

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB1@161 -46.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:26:22

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB162@0 -37.80 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:29:02

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB162@0 -47.15 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:28:07


70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@0 -47.32 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:29:53


70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@0 -38.03 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:30:48


70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@188 -37.92 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:32:34


70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@188 -47.28 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:31:39


70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB180@0 -47.39 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:33:30


70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB180@0 -36.92 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:34:25


70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -38.05 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:36:11


70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.45 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:35:16


70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@188 -46.23 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:37:02


70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@188 -37.84 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:37:57


70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB180@0 -38.16 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:39:43


70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB180@0 -47.16 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 12:38:48

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@0 -46.77 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:40:34

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@0 -37.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:41:29

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@188 -37.70 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:43:16

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@188 -46.40 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:42:21

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB180@0 -47.30 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:44:08

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB180@0 -37.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:45:02

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB1@0 -37.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:46:49

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB1@0 -47.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:45:54

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB1@216 -47.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:47:42

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB1@216 -37.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:48:36

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB216@0 -37.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:50:22

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB216@0 -47.33 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 12:49:28


80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.00 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:51:14


80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.43 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:52:09


80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@216 -46.48 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:53:01


80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@216 -38.03 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:53:56


80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB216@0 -37.69 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:55:43


80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB216@0 -47.38 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:54:48


80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@0 -37.21 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:57:30


80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@0 -47.04 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:56:35


80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@216 -37.34 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:59:17


80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@216 -47.56 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 12:58:22


80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB216@0 -47.29 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 13:00:08


80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB216@0 -37.66 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 13:01:03


90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@0 -44.86 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 13:29:13


90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@0 -37.83 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 13:30:08


90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@244 -37.76 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 13:31:57


90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@244 -47.62 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 13:31:02


90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB243@0 -47.04 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 13:32:51


90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB243@0 -38.12 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 13:33:46

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 13:35:35

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -45.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 13:34:40

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@244 -46.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 13:12:47

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@244 -37.73 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 13:13:42

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB243@0 -46.88 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 13:14:36

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB243@0 -37.68 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 13:15:31


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@0 -47.03 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 13:16:24


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@0 -37.72 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 13:17:19


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@244 -47.04 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 13:18:13


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@244 -37.52 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 13:19:09


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB243@0 -37.56 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 13:20:58


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB243@0 -46.86 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 13:20:03

100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 13:22:46

100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.88 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 13:21:51

100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@272 -37.95 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 13:24:35

100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@272 -45.80 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 13:23:40

100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB270@0 -46.65 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 13:25:28


100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB270@0 -38.11 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 13:26:23


n78_3

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0 -38.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 01:07:50

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0 -47.64 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 01:06:53

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB1@51 -47.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 01:09:12

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB1@51 -37.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 01:10:10

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB50@0 -37.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 05:59:11

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB50@0 -42.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 05:58:12

10MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -36.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:02:16

10MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -45.16 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:01:18

10MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@51 -37.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:04:10

10MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@51 -46.92 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:03:12

10MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB50@0 -37.95 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:06:03

10MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB50@0 -47.12 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:05:05

10MHz_15kHz_3795MHz_DFT-s-OFDM QPSK_RB1@0 -37.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:07:57

10MHz_15kHz_3795MHz_DFT-s-OFDM QPSK_RB1@0 -46.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:06:59

10MHz_15kHz_3795MHz_DFT-s-OFDM QPSK_RB1@51 -37.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:10:52

10MHz_15kHz_3795MHz_DFT-s-OFDM QPSK_RB1@51 -47.51 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:09:54

10MHz_15kHz_3795MHz_DFT-s-OFDM QPSK_RB50@0 -47.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:11:47

10MHz_15kHz_3795MHz_DFT-s-OFDM QPSK_RB50@0 -37.89 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:12:45


10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0 -38.38 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 17:52:18


10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0 -48.03 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 17:51:45


10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@23 -46.96 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 17:53:08


10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@23 -38.30 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 17:55:27


10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB24@0 -47.20 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 17:56:33


10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB24@0 -37.79 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 23.MAY.2024 17:57:30

10MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:17:12

10MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.70 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:41:27

10MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@23 -38.37 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:18:37

10MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@23 -46.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:18:08

10MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB24@0 -38.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:20:00

10MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB24@0 -45.99 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:19:28

10MHz_30kHz_3795MHz_DFT-s-OFDM QPSK_RB1@0 -46.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:08:39

10MHz_30kHz_3795MHz_DFT-s-OFDM QPSK_RB1@0 -37.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:09:36

10MHz_30kHz_3795MHz_DFT-s-OFDM QPSK_RB1@23 -37.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:12:21

10MHz_30kHz_3795MHz_DFT-s-OFDM QPSK_RB1@23 -46.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:11:24

10MHz_30kHz_3795MHz_DFT-s-OFDM QPSK_RB24@0 -46.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:13:11

10MHz_30kHz_3795MHz_DFT-s-OFDM QPSK_RB24@0 -37.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:14:07

15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.54 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:14:42

15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -38.12 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:15:40

15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@78 -46.66 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:16:36

15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@78 -37.95 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:17:35

15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB75@0 -46.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:18:31

15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB75@0 -37.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:19:29

15MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.37 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:20:36

15MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.69 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:21:34

15MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@78 -47.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:22:31

15MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@78 -37.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:23:29

15MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB75@0 -37.27 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:25:24

15MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB75@0 -46.60 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:24:26