



15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:27:36

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:26:37

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@78 -37.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:29:29

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@78 -47.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:28:31

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB75@0 -47.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:30:44

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB75@0 -37.88 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:31:42


15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.58 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 17:59:17


15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.34 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 17:58:21


15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@37 -47.29 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 18:00:08


15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@37 -37.58 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 18:01:04


15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB36@0 -47.35 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 18:01:55


15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB36@0 -37.57 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 23.MAY.2024 18:02:51

15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.76 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:20:50

15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -38.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:21:07

15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@37 -37.73 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:23:10

15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@37 -47.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:22:13

15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB36@0 -37.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:25:13

15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB36@0 -47.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:24:16

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:18:00

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:18:57

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@37 -45.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:19:46

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@37 -38.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:20:42

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB36@0 -47.27 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:21:32

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB36@0 -37.94 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:22:29

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:33:37

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.30 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:32:38

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@132 -46.95 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:34:32

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@132 -38.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:35:31

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB128@0 -38.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:37:24

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB128@0 -41.73 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:36:26

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:38:20

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.99 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:39:19

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@132 -38.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:41:13

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@132 -47.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:40:15

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB128@0 -37.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:43:08

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB128@0 -47.31 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:42:08

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:44:20

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:45:18

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@132 -47.68 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:46:31

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@132 -38.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:47:31

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB128@0 -47.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:48:47

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB128@0 -37.97 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:49:45

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.72 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:04:54

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:03:57

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@64 -47.27 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:05:44

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@64 -37.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:06:41

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB64@0 -37.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:08:46

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB64@0 -47.33 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:07:50


25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.89 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 19:27:00


25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.00 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 19:26:04


25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@64 -38.00 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 19:28:47


25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@64 -47.05 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 19:27:50


25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB64@0 -47.02 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 19:29:37


25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB64@0 -37.87 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 23.MAY.2024 19:30:34

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.54 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:23:19

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@0 -38.02 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 17:09:09

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@64 -47.02 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:25:05

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@64 -37.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 17:11:04

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB64@0 -47.43 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:27:35

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB64@0 -37.77 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 17:13:46

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -37.78 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:51:59

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -47.38 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:51:00

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@159 -37.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:54:12

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@159 -47.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:53:13

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB160@0 -37.77 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:56:22

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB160@0 -46.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:55:23

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:57:18

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -38.06 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 06:58:17

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@159 -47.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 07:00:25

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@159 -37.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 07:01:23

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB160@0 -46.76 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 07:02:20

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB160@0 -37.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 07:03:18

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB1@0 -47.43 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 07:04:27

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB1@0 -37.70 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 07:05:26

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB1@159 -47.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 07:06:22

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB1@159 -38.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 07:07:21

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB160@0 -37.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 07:09:16

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB160@0 -46.27 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 07:08:18

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -47.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:09:37

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -35.76 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:10:33

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@77 -47.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:11:23

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@77 -37.95 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:12:20

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB75@0 -37.73 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:14:07

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB75@0 -47.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:13:10

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:31:25

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.62 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:32:22

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@77 -46.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:33:12

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@77 -38.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:34:09

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB75@0 -46.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:35:00

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB75@0 -38.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:35:57

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@0 -38.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:30:18

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@0 -46.66 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:29:22

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@77 -47.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:32:11

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@77 -38.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:33:11

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB75@0 -47.45 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:34:09

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB75@0 -37.62 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:35:08


40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -46.71 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 07:10:13


40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -37.60 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 07:11:12


40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@215 -38.14 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 07:13:07


40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@215 -46.24 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 07:12:08


40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB216@0 -45.46 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 07:14:04


40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB216@0 -37.85 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 07:15:02


40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -38.05 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 08:07:17


40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.25 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 08:06:19


40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@215 -37.90 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 08:33:41


40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@215 -47.02 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 08:32:41


40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB216@0 -47.44 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng







Date: 23.MAY.2024 08:35:32

40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB216@0 -37.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 08:36:31




40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -37.97 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:15:54

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -46.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:14:58

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@105 -47.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:17:01

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@105 -38.12 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:17:58

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB100@0 -47.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:19:07

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB100@0 -38.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:20:03

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -38.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:37:44

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:36:47

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@105 -47.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:38:34

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@105 -38.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:42:20

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB100@0 -37.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:39:10

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB100@0 -47.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:38:11

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB1@0 -47.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:40:07

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB1@0 -37.95 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:41:06

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB1@105 -37.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:43:03

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB1@105 -47.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:42:05

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB100@0 -47.23 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:43:53

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB100@0 -37.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:44:50

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -41.90 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 08:42:25

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -37.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 08:43:23

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@269 -47.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 08:45:21

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@269 -37.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 08:46:20

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB270@0 -46.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 17:49:38

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB270@0 -38.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 17:50:53

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:10:51

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.88 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:09:55

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@269 -46.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:13:45

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@269 -37.97 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:14:01

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB270@0 -38.26 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:16:19

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB270@0 -47.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 19:15:46

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB1@0 -37.67 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:04:13

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB1@0 -46.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:03:17

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB1@269 -37.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:05:59

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB1@269 -47.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:05:03

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB270@0 -37.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:07:46

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB270@0 -47.62 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:06:49

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -37.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:21:51

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -46.73 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:20:54

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@132 -47.16 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:23:21

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@132 -37.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:24:17

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB128@0 -46.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:25:08

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB128@0 -37.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:26:05

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.45 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:45:40

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:46:37

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@132 -46.97 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:47:27

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@132 -37.68 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:48:24

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB128@0 -46.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:49:15

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB128@0 -37.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:50:12

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB1@0 -47.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:51:02

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB1@0 -38.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:51:59

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB1@132 -37.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:53:46

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB1@132 -47.38 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:52:49

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB128@0 -47.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:54:37

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB128@0 -38.14 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:55:33


60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0 -47.08 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 18:26:54


60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0 -38.04 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 18:27:51


60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@161 -37.67 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 18:29:38


60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@161 -46.34 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 18:28:42


60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB162@0 -46.82 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 18:30:29


60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB162@0 -37.61 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 23.MAY.2024 18:31:26

60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:57:21

60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:56:24

60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@161 -37.72 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:59:09

60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@161 -47.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:58:12

60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB162@0 -37.39 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 02:00:56

60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB162@0 -45.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 01:59:59


60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB1@0 -47.35 dBm




60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB1@0 -38.00 dBm




60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB1@161 -45.86 dBm




60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB1@161 -37.85 dBm




60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB162@0 -37.85 dBm



60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB162@0 -46.93 dBm




70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0 -46.16 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:32:17

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0 -37.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:33:14

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@188 -37.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:35:22

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@188 -46.91 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:34:25

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB180@0 -37.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:37:11

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB180@0 -47.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 18:36:14

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 02:10:13

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 02:11:10

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@188 -37.40 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 02:12:56

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@188 -47.10 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 02:12:00

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB180@0 -47.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 02:13:46

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB180@0 -37.66 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 24.MAY.2024 02:14:43


70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@0 -38.10 dBm




70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@0 -47.04 dBm




70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@188 -47.81 dBm



70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@188 -37.27 dBm



70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB180@0 -37.62 dBm



70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB180@0 -47.45 dBm

