



ax20_5720MHz_RU_52/40_Chain 0 -0.17 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:52:45

ax20_5720MHz_RU_52/40_Chain 1 0.94 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:06:36

ax20_5720MHz_RU_106/54_Chain 0 -5.19 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:53:24

ax20_5720MHz_RU_106/54_Chain 1 -4.98 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:07:04

ax20_5720MHz_RU_242/61_Chain 0 -8.11 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:53:56

ax20_5720MHz_RU_242/61_Chain 1 -7.28 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:07:48

ax40_5510MHz_RU_26/0_Chain 0 3.28 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:55:41

ax40_5510MHz_RU_26/0_Chain 1 3.78 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:08:38

ax40_5510MHz_RU_52/37_Chain 0 -1.05 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:56:23

ax40_5510MHz_RU_52/37_Chain 1 -0.41 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:12:17

ax40_5510MHz_RU_106/53_Chain 0 -5.10 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:57:50

ax40_5510MHz_RU_106/53_Chain 1 -5.25 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:12:58

ax40_5510MHz_RU_242/61_Chain 0 -8.52 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:58:46

ax40_5510MHz_RU_242/61_Chain 1 -8.48 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:13:33

ax40_5510MHz_RU_484/65_Chain 0 -11.52 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 16:59:29

ax40_5510MHz_RU_484/65_Chain 1 -11.73 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:14:07

ax40_5550MHz_RU_26/0_Chain 0 2.66 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:02:56

ax40_5550MHz_RU_26/0_Chain 1 3.19 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:15:15

ax40_5550MHz_RU_52/37_Chain 0 -1.66 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:03:32

ax40_5550MHz_RU_52/37_Chain 1 -1.19 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:15:46

ax40_5550MHz_RU_106/53_Chain 0 -5.76 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:04:08

ax40_5550MHz_RU_106/53_Chain 1 -5.92 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:16:39

ax40_5550MHz_RU_242/61_Chain 0 -9.26 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:04:44

ax40_5550MHz_RU_242/61_Chain 1 -8.57 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:17:15


ax40_5550MHz_RU_484/65_Chain 0 -11.75 dBm




ax40_5550MHz_RU_484/65_Chain 1 -11.72 dBm




ax40_5670MHz_RU_26/17_Chain 0 3.35 dBm




ax40_5670MHz_RU_26/17_Chain 1 3.75 dBm




ax40_5670MHz_RU_52/44_Chain 0 -1.65 dBm



ax40_5670MHz_RU_52/44_Chain 1 -1.28 dBm




ax40_5670MHz_RU_106/56_Chain 0 -5.96 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:07:48

ax40_5670MHz_RU_106/56_Chain 1 -5.45 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:22:16

ax40_5670MHz_RU_242/62_Chain 0 -9.04 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:08:31

ax40_5670MHz_RU_242/62_Chain 1 -8.43 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:22:41

ax40_5670MHz_RU_484/65_Chain 0 -12.08 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:09:06

ax40_5670MHz_RU_484/65_Chain 1 -11.87 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:23:04

ax40_5710MHz_RU_26/17_Chain 0 3.06 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:09:39

ax40_5710MHz_RU_26/17_Chain 1 3.49 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:24:06

ax40_5710MHz_RU_52/44_Chain 0 -1.13 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:13:41

ax40_5710MHz_RU_52/44_Chain 1 -0.96 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:24:42

ax40_5710MHz_RU_106/56_Chain 0 -5.45 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:15:16

ax40_5710MHz_RU_106/56_Chain 1 -4.75 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:25:22

ax40_5710MHz_RU_242/62_Chain 0 -9.31 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:16:54

ax40_5710MHz_RU_242/62_Chain 1 -7.60 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:26:52

ax40_5710MHz_RU_484/65_Chain 0 -12.70 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:17:20

ax40_5710MHz_RU_484/65_Chain 1 -11.12 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:27:24

ax80_5530MHz_RU_26/0_Chain 0 3.17 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:26:29

ax80_5530MHz_RU_26/0_Chain 1 3.20 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:28:17

ax80_5530MHz_RU_52/37_Chain 0 -0.64 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:27:07

ax80_5530MHz_RU_52/37_Chain 1 -0.26 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:30:30

ax80_5530MHz_RU_106/53_Chain 0 -5.80 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:31:23

ax80_5530MHz_RU_106/53_Chain 1 -5.30 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:29:18

ax80_5530MHz_RU_242/61_Chain 0 -8.81 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:32:18

ax80_5530MHz_RU_242/61_Chain 1 -8.70 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:29:54


ax80_5530MHz_RU_484/65_Chain 0 -11.80 dBm




ax80_5530MHz_RU_484/65_Chain 1 -12.03 dBm




ax80_5530MHz_RU_996/67_Chain 0 -14.60 dBm




ax80_5530MHz_RU_996/67_Chain 1 -14.70 dBm




ax80_5610MHz_RU_26/0_Chain 0 2.41 dBm



ax80_5610MHz_RU_26/0_Chain 1 3.37 dBm




ax80_5610MHz_RU_52/37_Chain 0 -2.43 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:34:59

ax80_5610MHz_RU_52/37_Chain 1 -1.88 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:32:19

ax80_5610MHz_RU_106/53_Chain 0 -5.62 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:35:31

ax80_5610MHz_RU_106/53_Chain 1 -6.21 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:32:52

ax80_5610MHz_RU_242/61_Chain 0 -10.03 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:36:01

ax80_5610MHz_RU_242/61_Chain 1 -9.46 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:33:46

ax80_5610MHz_RU_484/65_Chain 0 -12.56 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:36:28

ax80_5610MHz_RU_484/65_Chain 1 -12.47 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:34:17

ax80_5610MHz_RU_996/67_Chain 0 -14.85 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:36:56

ax80_5610MHz_RU_996/67_Chain 1 -15.20 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:35:36

ax80_5690MHz_RU_26/36_Chain 0 2.67 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:37:37

ax80_5690MHz_RU_26/36_Chain 1 3.43 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:36:14

ax80_5690MHz_RU_52/52_Chain 0 -1.82 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:38:12

ax80_5690MHz_RU_52/52_Chain 1 -1.81 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:36:45

ax80_5690MHz_RU_106/60_Chain 0 -5.78 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:38:47

ax80_5690MHz_RU_106/60_Chain 1 -5.29 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:37:14

ax80_5690MHz_RU_242/64_Chain 0 -8.68 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:39:18

ax80_5690MHz_RU_242/64_Chain 1 -8.49 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:37:50

ax80_5690MHz_RU_484/66_Chain 0 -12.31 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
 Date: 6.JUN.2024 17:39:49

ax80_5690MHz_RU_484/66_Chain 1 -10.31 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
 Date: 4.JUN.2024 19:39:39

ax80_5690MHz_RU_996/67_Chain 0 -14.77 dBm



Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
 Date: 6.JUN.2024 17:40:29


ax80_5690MHz_RU_996/67_Chain 1 -14.27 dBm



Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
 Date: 4.JUN.2024 19:40:18


5.8G

a_5745MHz_Chain 0 2.11 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
 Date: 6.JUN.2024 17:48:08

a_5745MHz_Chain 1 3.59 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
 Date: 4.JUN.2024 19:42:45

a_5785MHz_Chain 0 1.91 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:48:38

a_5785MHz_Chain 1 3.69 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:44:01

a_5825MHz_Chain 0 2.22 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:49:08

a_5825MHz_Chain 1 3.95 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:45:18

n20_5745MHz_Chain 0 1.98 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:50:58

n20_5745MHz_Chain 1 2.37 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 7.JUN.2024 10:28:12

n20_5785MHz_Chain 0 1.45 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:51:28

n20_5785MHz_Chain 1 2.43 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:49:32

n20_5825MHz_Chain 0 1.95 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:51:58

n20_5825MHz_Chain 1 2.56 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:50:42

n40_5755MHz_Chain 0 -0.76 dBm



Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 17:52:33

n40_5755MHz_Chain 1 -0.04 dBm



Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 4.JUN.2024 19:52:37