



n40_5795MHz_Chain 0 -0.67 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
 Date: 6.JUN.2024 17:53:05

n40_5795MHz_Chain 1 0.04 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
 Date: 4.JUN.2024 19:54:13

ac80_5775MHz_Chain 0 -5.49 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
 Date: 6.JUN.2024 17:55:19

ac80_5775MHz_Chain 1 -5.38 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
 Date: 4.JUN.2024 19:55:58

ax20_5745MHz_RU_26/0_Chain 0 2.79 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
 Date: 6.JUN.2024 18:38:03

ax20_5745MHz_RU_26/0_Chain 1 3.63 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
 Date: 6.JUN.2024 18:37:08

ax20_5745MHz_RU_52/37_Chain 0 -0.99 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 18:38:35

ax20_5745MHz_RU_52/37_Chain 1 -0.83 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:17:19

ax20_5745MHz_RU_106/53_Chain 0 -6.29 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 18:50:25

ax20_5745MHz_RU_106/53_Chain 1 -5.63 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:17:43

ax20_5745MHz_RU_242/61_Chain 0 -10.45 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 18:51:31

ax20_5745MHz_RU_242/61_Chain 1 -9.80 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:04:00

ax20_5785MHz_RU_26/0_Chain 0 2.50 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 18:52:28

ax20_5785MHz_RU_26/0_Chain 1 2.80 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:18:38

ax20_5785MHz_RU_52/37_Chain 0 -1.58 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 18:52:59

ax20_5785MHz_RU_52/37_Chain 1 -1.90 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:19:06

ax20_5785MHz_RU_106/53_Chain 0 -6.48 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 18:54:04

ax20_5785MHz_RU_106/53_Chain 1 -6.41 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:19:29

ax20_5785MHz_RU_242/61_Chain 0 -11.37 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 18:54:41

ax20_5785MHz_RU_242/61_Chain 1 -11.43 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:19:54

ax20_5825MHz_RU_26/8_Chain 0 2.47 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 18:55:54

ax20_5825MHz_RU_26/8_Chain 1 2.61 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:22:38

ax20_5825MHz_RU_52/40_Chain 0 -1.20 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 18:56:22

ax20_5825MHz_RU_52/40_Chain 1 0.56 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:12:47

ax20_5825MHz_RU_106/54_Chain 0 -6.89 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 18:57:46

ax20_5825MHz_RU_106/54_Chain 1 -6.51 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:23:36

ax20_5825MHz_RU_242/61_Chain 0 -10.93 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 18:58:16

ax20_5825MHz_RU_242/61_Chain 1 -10.63 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:13:48

ax40_5755MHz_RU_26/0_Chain 0 1.07 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:19:19

ax40_5755MHz_RU_26/0_Chain 1 3.05 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:25:35

ax40_5755MHz_RU_52/37_Chain 0 -2.31 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:19:46

ax40_5755MHz_RU_52/37_Chain 1 -1.27 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:26:16

ax40_5755MHz_RU_106/53_Chain 0 -7.33 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:20:27

ax40_5755MHz_RU_106/53_Chain 1 -5.75 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:29:33

ax40_5755MHz_RU_242/61_Chain 0 -12.91 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:21:34

ax40_5755MHz_RU_242/61_Chain 1 -10.98 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:30:09

ax40_5755MHz_RU_484/65_Chain 0 -14.44 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:22:06

ax40_5755MHz_RU_484/65_Chain 1 -13.80 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:30:44

ax40_5795MHz_RU_26/17_Chain 0 1.44 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:25:39

ax40_5795MHz_RU_26/17_Chain 1 2.67 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:32:47

ax40_5795MHz_RU_52/44_Chain 0 -2.00 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:26:15

ax40_5795MHz_RU_52/44_Chain 1 -1.08 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:33:13

ax40_5795MHz_RU_106/56_Chain 0 -6.91 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:27:51

ax40_5795MHz_RU_106/56_Chain 1 -6.79 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:33:56

ax40_5795MHz_RU_242/62_Chain 0 -12.19 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:31:55

ax40_5795MHz_RU_242/62_Chain 1 -11.11 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:34:40

ax40_5795MHz_RU_484/65_Chain 0 -14.07 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:33:25

ax40_5795MHz_RU_484/65_Chain 1 -13.30 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:35:07

ax80_5775MHz_RU_26/0_Chain 0 2.17 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:34:33

ax80_5775MHz_RU_26/0_Chain 1 3.21 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:36:19

ax80_5775MHz_RU_52/37_Chain 0 -2.38 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:37:15

ax80_5775MHz_RU_52/37_Chain 1 -1.01 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:37:07

ax80_5775MHz_RU_106/53_Chain 0 -6.89 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:37:50

ax80_5775MHz_RU_106/53_Chain 1 -6.19 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:37:43

ax80_5775MHz_RU_242/61_Chain 0 -12.26 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:39:31

ax80_5775MHz_RU_242/61_Chain 1 -11.66 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:38:42

ax80_5775MHz_RU_484/65_Chain 0 -14.99 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:39:59

ax80_5775MHz_RU_484/65_Chain 1 -14.52 dBm




Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:39:22

ax80_5775MHz_RU_996/67_Chain 0 -17.57 dBm



Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 6.JUN.2024 19:40:30

ax80_5775MHz_RU_996/67_Chain 1 -16.96 dBm



Comment: ProjectNo.:2403S73382E-RF Tester:Lingling Li
Date: 5.JUN.2024 10:40:06