



70MHz_30kHz_3500MHz_CP-OFDM 16 QAM_RB189@0 68.075 MHz




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 18:30:08

70MHz_30kHz_3500MHz_CP-OFDM 256 QAM_RB189@0 68.379 MHz




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 18:31:08

70MHz_30kHz_3500MHz_CP-OFDM 64 QAM_RB189@0 68.075 MHz




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 18:30:37

70MHz_30kHz_3500MHz_CP-OFDM QPSK_RB189@0 67.771 MHz




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 18:29:39

70MHz_30kHz_3500MHz_DFT-s-OFDM 16 QAM_RB180@0 64.732 MHz




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 18:28:07

70MHz_30kHz_3500MHz_DFT-s-OFDM 256 QAM_RB180@0 65.340 MHz




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 18:29:06

70MHz_30kHz_3500MHz_DFT-s-OFDM 64 QAM_RB180@0 64.732 MHz




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 18:28:36

70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB180@0 64.732 MHz




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 18:27:38

70MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$ BPSK_RB180@0 64.732 MHz




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 18:27:00

80MHz_30kHz_3500MHz_CP-OFDM 16 QAM_RB217@0 77.169 MHz




80MHz_30kHz_3500MHz_CP-OFDM 256 QAM_RB217@0 77.181 MHz



80MHz_30kHz_3500MHz_CP-OFDM 64 QAM_RB217@0 77.154 MHz




80MHz_30kHz_3500MHz_CP-OFDM QPSK_RB217@0 77.188 MHz




80MHz_30kHz_3500MHz_DFT-s-OFDM 16 QAM_RB216@0 77.141 MHz




80MHz_30kHz_3500MHz_DFT-s-OFDM 256 QAM_RB216@0 76.919 MHz



80MHz_30kHz_3500MHz_DFT-s-OFDM 64 QAM_RB216@0 76.951 MHz




80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB216@0 76.870 MHz

80MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$ BPSK_RB216@0 76.833 MHz


90MHz_30kHz_3500MHz_CP-OFDM 16 QAM_RB245@0 87.124 MHz



90MHz_30kHz_3500MHz_CP-OFDM 256 QAM_RB245@0 87.258 MHz




90MHz_30kHz_3500MHz_CP-OFDM 64 QAM_RB245@0 87.206 MHz




90MHz_30kHz_3500MHz_CP-OFDM QPSK_RB245@0 87.203 MHz




90MHz_30kHz_3500MHz_DFT-s-OFDM 16 QAM_RB243@0 86.877 MHz




90MHz_30kHz_3500MHz_DFT-s-OFDM 256 QAM_RB243@0 86.479 MHz




90MHz_30kHz_3500MHz_DFT-s-OFDM 64 QAM_RB243@0 86.545 MHz




90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB243@0 86.559 MHz

90MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$ BPSK_RB243@0 86.579 MHz


100MHz_30kHz_3500MHz_CP-OFDM 16 QAM_RB273@0 97.256 MHz




100MHz_30kHz_3500MHz_CP-OFDM 256 QAM_RB273@0 96.995 MHz




100MHz_30kHz_3500MHz_CP-OFDM 64 QAM_RB273@0 96.934 MHz




100MHz_30kHz_3500MHz_CP-OFDM QPSK_RB273@0 96.971 MHz




100MHz_30kHz_3500MHz_DFT-s-OFDM 16 QAM_RB270@0 96.599 MHz





100MHz_30kHz_3500MHz_DFT-s-OFDM 256 QAM_RB270@0 96.490 MHz



100MHz_30kHz_3500MHz_DFT-s-OFDM 64 QAM_RB270@0 96.524 MHz




100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB270@0 96.192 MHz


100MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$ BPSK_RB270@0 96.180 MHz

n78_3


10MHz_15kHz_3750MHz_CP-OFDM 16 QAM_RB52@0 9.258 MHz




10MHz_15kHz_3750MHz_CP-OFDM 256 QAM_RB52@0 9.259 MHz




10MHz_15kHz_3750MHz_CP-OFDM 64 QAM_RB52@0 9.294 MHz




10MHz_15kHz_3750MHz_CP-OFDM QPSK_RB52@0 9.286 MHz




10MHz_15kHz_3750MHz_DFT-s-OFDM 16 QAM_RB50@0 9.178 MHz





10MHz_15kHz_3750MHz_DFT-s-OFDM 256 QAM_RB50@0 9.202 MHz




10MHz_15kHz_3750MHz_DFT-s-OFDM 64 QAM_RB50@0 9.206 MHz




10MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB50@0 9.210 MHz

10MHz_15kHz_3750MHz_DFT-s-OFDM $\pi/2$ BPSK_RB50@0 9.207 MHz


10MHz_30kHz_3750MHz_CP-OFDM 16 QAM_RB24@0 8.571 MHz




10MHz_30kHz_3750MHz_CP-OFDM 256 QAM_RB24@0 8.572 MHz




10MHz_30kHz_3750MHz_CP-OFDM 64 QAM_RB24@0 8.572 MHz




10MHz_30kHz_3750MHz_CP-OFDM QPSK_RB24@0 8.565 MHz




10MHz_30kHz_3750MHz_DFT-s-OFDM 16 QAM_RB24@0 8.568 MHz





10MHz_30kHz_3750MHz_DFT-s-OFDM 256 QAM_RB24@0 8.578 MHz




10MHz_30kHz_3750MHz_DFT-s-OFDM 64 QAM_RB24@0 8.573 MHz




10MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB24@0 8.608 MHz

10MHz_30kHz_3750MHz_DFT-s-OFDM $\pi/2$ BPSK_RB24@0 8.572 MHz


15MHz_15kHz_3750MHz_CP-OFDM 16 QAM_RB79@0 14.056 MHz




15MHz_15kHz_3750MHz_CP-OFDM 256 QAM_RB79@0 14.069 MHz




15MHz_15kHz_3750MHz_CP-OFDM 64 QAM_RB79@0 14.101 MHz




15MHz_15kHz_3750MHz_CP-OFDM QPSK_RB79@0 14.057 MHz




15MHz_15kHz_3750MHz_DFT-s-OFDM 16 QAM_RB75@0 13.981 MHz





15MHz_15kHz_3750MHz_DFT-s-OFDM 256 QAM_RB75@0 13.946 MHz




15MHz_15kHz_3750MHz_DFT-s-OFDM 64 QAM_RB75@0 13.939 MHz




15MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB75@0 13.936 MHz

15MHz_15kHz_3750MHz_DFT-s-OFDM $\pi/2$ BPSK_RB75@0 13.946 MHz


15MHz_30kHz_3750MHz_CP-OFDM 16 QAM_RB38@0 13.562 MHz




15MHz_30kHz_3750MHz_CP-OFDM 256 QAM_RB38@0 13.572 MHz




15MHz_30kHz_3750MHz_CP-OFDM 64 QAM_RB38@0 13.570 MHz




15MHz_30kHz_3750MHz_CP-OFDM QPSK_RB36@0 13.561 MHz




15MHz_30kHz_3750MHz_DFT-s-OFDM 16 QAM_RB36@0 13.566 MHz





15MHz_30kHz_3750MHz_DFT-s-OFDM 256 QAM_RB36@0 13.450 MHz




15MHz_30kHz_3750MHz_DFT-s-OFDM 64 QAM_RB36@0 13.469 MHz




15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB36@0 13.453 MHz

15MHz_30kHz_3750MHz_DFT-s-OFDM $\pi/2$ BPSK_RB36@0 13.506 MHz


25MHz_15kHz_3750MHz_CP-OFDM 16 QAM_RB133@0 23.724 MHz




25MHz_15kHz_3750MHz_CP-OFDM 256 QAM_RB133@0 23.643 MHz




25MHz_15kHz_3750MHz_CP-OFDM 64 QAM_RB133@0 23.710 MHz




25MHz_15kHz_3750MHz_CP-OFDM QPSK_RB133@0 23.716 MHz




25MHz_15kHz_3750MHz_DFT-s-OFDM 16 QAM_RB128@0 23.438 MHz





25MHz_15kHz_3750MHz_DFT-s-OFDM 256 QAM_RB128@0 23.532 MHz




25MHz_15kHz_3750MHz_DFT-s-OFDM 64 QAM_RB128@0 23.441 MHz




25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB128@0 23.331 MHz

25MHz_15kHz_3750MHz_DFT-s-OFDM $\pi/2$ BPSK_RB128@0 23.529 MHz


25MHz_30kHz_3750MHz_CP-OFDM 16 QAM_RB65@0 23.132 MHz




25MHz_30kHz_3750MHz_CP-OFDM 256 QAM_RB65@0 23.227 MHz




25MHz_30kHz_3750MHz_CP-OFDM 64 QAM_RB65@0 23.220 MHz




25MHz_30kHz_3750MHz_CP-OFDM QPSK_RB65@0 23.211 MHz




25MHz_30kHz_3750MHz_DFT-s-OFDM 16 QAM_RB64@0 23.021 MHz




25MHz_30kHz_3750MHz_DFT-s-OFDM 256 QAM_RB64@0 23.027 MHz




25MHz_30kHz_3750MHz_DFT-s-OFDM 64 QAM_RB64@0 23.038 MHz




25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB64@0 23.036 MHz

25MHz_30kHz_3750MHz_DFT-s-OFDM $\pi/2$ BPSK_RB64@0 22.923 MHz


30MHz_15kHz_3750MHz_CP-OFDM 16 QAM_RB160@0 28.467 MHz




30MHz_15kHz_3750MHz_CP-OFDM 256 QAM_RB160@0 28.496 MHz




30MHz_15kHz_3750MHz_CP-OFDM 64 QAM_RB160@0 28.493 MHz




30MHz_15kHz_3750MHz_CP-OFDM QPSK_RB160@0 28.471 MHz




30MHz_15kHz_3750MHz_DFT-s-OFDM 16 QAM_RB160@0 28.578 MHz





30MHz_15kHz_3750MHz_DFT-s-OFDM 256 QAM_RB160@0 28.454 MHz




30MHz_15kHz_3750MHz_DFT-s-OFDM 64 QAM_RB160@0 28.580 MHz




30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB160@0 28.485 MHz

30MHz_15kHz_3750MHz_DFT-s-OFDM $\pi/2$ BPSK_RB160@0 28.482 MHz

30MHz_30kHz_3750MHz_CP-OFDM 16 QAM_RB78@0 27.757 MHz



30MHz_30kHz_3750MHz_CP-OFDM 256 QAM_RB78@0 27.748 MHz



30MHz_30kHz_3750MHz_CP-OFDM 64 QAM_RB78@0 27.774 MHz

