



20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB1@0 -47.50 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:14:48

20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB1@0 -35.43 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:15:50

20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB1@50 -46.92 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:16:53

20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB1@50 -35.70 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:17:56

20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB50@0 -46.59 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:18:58

20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB50@0 -35.39 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:20:07

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -47.34 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 21:56:09

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -35.84 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 21:57:10

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@159 -35.60 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:02:17

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@159 -46.75 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:01:16

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB160@0 -35.20 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:04:52

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB160@0 -47.30 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:03:51

30MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -46.85 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:08:00

30MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.50 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:09:01

30MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@159 -46.96 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:20:43

30MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@159 -35.57 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:21:51

30MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB160@0 -47.54 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:24:49

30MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB160@0 -35.29 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:25:51

30MHz_15kHz_3965MHz_DFT-s-OFDM QPSK_RB1@0 -46.86 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:28:32

30MHz_15kHz_3965MHz_DFT-s-OFDM QPSK_RB1@0 -35.60 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:29:33

30MHz_15kHz_3965MHz_DFT-s-OFDM QPSK_RB1@159 -35.49 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:31:36

30MHz_15kHz_3965MHz_DFT-s-OFDM QPSK_RB1@159 -47.31 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:30:34

30MHz_15kHz_3965MHz_DFT-s-OFDM QPSK_RB160@0 -35.14 dBm









ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:33:38


30MHz_15kHz_3965MHz_DFT-s-OFDM QPSK_RB160@0 -47.12 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:32:36




40MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.00 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:41:46

40MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -46.77 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:40:45

40MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@215 -46.69 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:42:48

40MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@215 -35.60 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:43:49

40MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB216@0 -35.21 dBm









ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:45:50


40MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB216@0 -47.36 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:44:49




40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -35.56 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:34:08

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -47.26 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:33:03

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@105 -35.32 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:36:23

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@105 -46.87 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:35:18

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB100@0 -47.47 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:37:33

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB100@0 -35.72 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:38:38

40MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.21 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:39:49

40MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.22 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:40:53

40MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@105 -35.62 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:43:09

40MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@105 -47.24 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:42:03

40MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB100@0 -46.86 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:44:58

40MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB100@0 -34.83 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:46:00

40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB1@0 -47.24 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:47:41

40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB1@0 -35.48 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:48:44

40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB1@105 -46.53 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:49:47

40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB1@105 -35.31 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:50:49

40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB100@0 -46.86 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:51:52

40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB100@0 -35.18 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:52:54

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -35.40 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:55:02

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -47.49 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:54:00

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@269 -47.35 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:56:21

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@269 -35.69 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:57:22

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB270@0 -46.48 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:58:23

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB270@0 -35.46 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 22:59:24

50MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -46.66 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 23:01:25

50MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.60 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 23:02:27

50MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@269 -35.56 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 23:07:44

50MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@269 -47.05 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 23:06:43

50MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB270@0 -47.28 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 23:08:59

50MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB270@0 -34.86 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 23:10:01

50MHz_15kHz_3955MHz_DFT-s-OFDM QPSK_RB1@0 -35.34 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 23:23:47

50MHz_15kHz_3955MHz_DFT-s-OFDM QPSK_RB1@0 -46.81 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 23:22:46

50MHz_15kHz_3955MHz_DFT-s-OFDM QPSK_RB1@269 -34.81 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 23:17:21

50MHz_15kHz_3955MHz_DFT-s-OFDM QPSK_RB1@269 -47.24 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 23:16:19

50MHz_15kHz_3955MHz_DFT-s-OFDM QPSK_RB270@0 -35.28 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 23:19:23

50MHz_15kHz_3955MHz_DFT-s-OFDM QPSK_RB270@0 -45.95 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 7.MAY.2024 23:18:21

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -45.88 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:53:56

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -34.74 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:54:58

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@132 -35.84 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:57:03

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@132 -47.14 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:56:02

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB128@0 -34.70 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:59:08

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB128@0 -47.03 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 08:58:06

50MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.58 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:01:17

50MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.67 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:00:11

50MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@132 -47.34 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:02:20

50MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@132 -34.97 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:03:22

50MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB128@0 -47.55 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:04:25

50MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB128@0 -35.60 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:05:27

50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB1@0 -35.46 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:07:52

50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB1@0 -47.29 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:06:50

50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB1@132 -35.58 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:09:57

50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB1@132 -46.67 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:08:55

50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB128@0 -35.39 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:12:34

50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB128@0 -47.53 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:11:32

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0 -35.01 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:14:40

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0 -47.37 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:13:37

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@161 -46.65 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:15:43

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@161 -35.24 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:16:45

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB162@0 -35.62 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:19:20

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB162@0 -47.33 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:18:18

60MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -34.63 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:21:29

60MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.06 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:20:26

60MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@161 -46.76 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:23:20

60MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@161 -35.29 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:24:23

60MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB162@0 -46.95 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:25:25

60MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB162@0 -34.93 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:26:27

60MHz_30kHz_3950MHz_DFT-s-OFDM QPSK_RB1@0 -47.51 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:27:49

60MHz_30kHz_3950MHz_DFT-s-OFDM QPSK_RB1@0 -35.33 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:28:51

60MHz_30kHz_3950MHz_DFT-s-OFDM QPSK_RB1@161 -35.13 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:30:58

60MHz_30kHz_3950MHz_DFT-s-OFDM QPSK_RB1@161 -46.45 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:29:55

60MHz_30kHz_3950MHz_DFT-s-OFDM QPSK_RB162@0 -46.63 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:32:01

60MHz_30kHz_3950MHz_DFT-s-OFDM QPSK_RB162@0 -35.67 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:33:03

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0 -46.83 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:34:06

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0 -35.27 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:35:09

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@188 -35.37 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:37:31

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@188 -47.08 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:36:29

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB180@0 -47.03 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:38:45

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB180@0 -35.18 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:39:48

70MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -34.99 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:42:12

70MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.48 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:41:09

70MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@188 -47.56 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:43:46

70MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@188 -35.39 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:44:48

70MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB180@0 -35.04 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:47:08

70MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB180@0 -47.71 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:46:05

70MHz_30kHz_3945MHz_DFT-s-OFDM QPSK_RB1@0 -35.27 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:49:18

70MHz_30kHz_3945MHz_DFT-s-OFDM QPSK_RB1@0 -47.17 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:48:12

70MHz_30kHz_3945MHz_DFT-s-OFDM QPSK_RB1@188 -35.38 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:51:41

70MHz_30kHz_3945MHz_DFT-s-OFDM QPSK_RB1@188 -47.06 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:50:38

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@0 -46.85 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:54:23

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@0 -35.43 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:55:25

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@216 -35.10 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:57:34

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@216 -46.92 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:56:31

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB216@0 -35.36 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 10:00:10

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB216@0 -47.19 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 09:59:08

80MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.72 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:12:45

80MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.45 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:13:46

80MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@216 -35.62 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:16:03

80MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@216 -46.02 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:15:00

80MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB216@0 -35.68 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:18:22

80MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB216@0 -47.23 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:17:21

80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB1@0 -35.18 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 10:02:20

80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB1@0 -46.96 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 10:01:17

80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB1@216 -47.69 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:23:43

80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB1@216 -35.31 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:24:45

80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB216@0 -35.17 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:27:01

80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB216@0 -46.23 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:26:00

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB1@0 -46.76 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:28:02

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB1@0 -35.98 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:29:04

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB1@244 -35.23 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:31:24

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB1@244 -46.82 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:30:23

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB243@0 -47.65 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:33:49

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB243@0 -34.51 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:34:51

90MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.00 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:37:23

90MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.29 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:38:25

90MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@244 -46.91 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:40:58

90MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@244 -34.64 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:41:59

90MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB243@0 -35.38 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:45:13

90MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB243@0 -46.61 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:44:11

90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB1@0 -45.13 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:47:28

90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB1@0 -35.66 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:48:30

90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB1@244 -47.49 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:49:32

90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB1@244 -35.60 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:50:33

90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB243@0 -35.46 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:52:37

90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB243@0 -47.39 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:51:35

100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -35.06 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:54:57

100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.58 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:53:55

100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@272 -46.52 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:56:19

100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@272 -34.83 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:57:21

100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB270@0 -35.36 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 04:00:29

100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB270@0 -46.95 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 03:59:28

100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -45.78 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 04:03:24

100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.23 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 04:04:26

100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@272 -35.53 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 04:06:43

100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@272 -46.58 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 04:05:40

100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB270@0 -35.27 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 04:09:25

100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB270@0 -46.97 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 04:08:24

100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB1@0 -35.63 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 04:12:58

100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB1@0 -47.16 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 04:11:57

100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB1@272 -47.59 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 04:14:00

100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB1@272 -35.39 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 04:15:01

100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB270@0 -35.22 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 04:17:18


100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB270@0 -46.96 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 04:16:17


n78_1

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@0 -37.33 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:22:34

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@0 -47.28 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:21:41

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@23 -37.00 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:24:17

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@23 -47.00 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:23:24

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB24@0 -46.98 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:25:08

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB24@0 -37.48 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:26:01

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.96 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:28:12

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.36 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:27:19

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@23 -47.26 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:30:04

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@23 -37.98 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:30:57

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB24@0 -46.68 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:32:45

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB24@0 -37.83 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:33:39

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@0 -37.98 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:35:24

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@0 -47.28 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:34:30

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@23 -37.75 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:37:43

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@23 -46.15 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:36:47

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB24@0 -37.81 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:40:28

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB24@0 -47.45 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:39:34

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.07 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:41:48

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.41 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:42:42

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@37 -47.27 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:43:33

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@37 -37.88 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:44:26

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB36@0 -37.55 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:46:10

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB36@0 -47.39 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:45:16

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.44 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:47:35

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -38.23 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 6.MAY.2024 15:48:29