



15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@78 -37.72 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 10:53:23

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@78 -47.50 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 10:52:27

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB75@0 -37.98 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 10:55:11

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB75@0 -46.68 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 10:54:14

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.91 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 12:31:06

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.90 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 12:30:09

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@37 -37.71 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 12:33:13

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@37 -47.07 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 12:32:16

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB36@0 -47.10 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 15:42:12

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB36@0 -37.70 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 15:45:37

15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.51 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 15:46:51

15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.56 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 15:47:49


15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@37 -37.40 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 12:41:25


15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@37 -46.70 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 12:40:29


15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB36@0 -47.21 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 12:42:16


15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB36@0 -37.88 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 12:43:13


15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.78 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 12:44:03


15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.99 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng


Date: 8.MAY.2024 12:45:00

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@37 -37.61 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 12:46:47

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@37 -47.20 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 12:45:51

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB36@0 -37.83 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 12:48:36

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB36@0 -47.32 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 12:47:39

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.50 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 10:57:00

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.64 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 10:56:03

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@132 -37.74 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 10:58:48

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@132 -47.46 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 10:57:52

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB128@0 -47.53 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 10:59:38

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB128@0 -37.83 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:00:35

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.87 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:02:24

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.63 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:01:25

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@132 -37.61 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:04:10

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@132 -47.52 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:03:14

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB128@0 -46.52 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:05:01

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB128@0 -38.04 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:05:58

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.69 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:07:47

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.81 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:06:49


25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@132 -47.19 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 11:08:42


25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@132 -37.15 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 11:09:39


25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB128@0 -37.84 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 11:11:28


25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB128@0 -47.01 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 11:10:31


25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.48 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 12:49:27


25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.51 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng


Date: 8.MAY.2024 12:50:24

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@64 -37.73 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 15:50:10

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@64 -47.82 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 15:49:12

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB64@0 -37.14 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 15:52:24

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB64@0 -46.36 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 15:51:25

25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.14 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 15:53:17

25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.92 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 15:54:15

25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@64 -37.93 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:02:19

25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@64 -45.92 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:01:22

25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB64@0 -37.88 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:04:09

25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB64@0 -46.68 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:03:11

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.64 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:05:59

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.35 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:05:02

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@64 -46.37 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:06:52

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@64 -37.77 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:07:49

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB64@0 -37.78 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:09:39

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB64@0 -47.12 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:08:41

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -46.77 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:12:18

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -38.14 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:13:14

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@159 -47.30 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:14:07

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@159 -37.49 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:15:03

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB160@0 -37.98 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:16:55

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB160@0 -47.53 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:15:58

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.25 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 15:30:59

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.85 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 15:31:56

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@159 -47.28 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:21:29

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@159 -37.92 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:22:25

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB160@0 -38.18 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:25:13

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB160@0 -47.30 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:24:16

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB1@0 -46.45 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:26:03

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB1@0 -37.58 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:27:00

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB1@159 -37.68 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:28:48

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB1@159 -47.69 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:27:51

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB160@0 -37.85 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:30:38

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB160@0 -46.82 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:29:41

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -47.44 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:10:32

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -37.70 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:11:28

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@77 -47.10 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:12:37

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@77 -37.91 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:13:34

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB75@0 -47.55 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:14:26

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB75@0 -37.59 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:15:24

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.11 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:16:35

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.60 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:17:33

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@77 -37.86 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:19:23

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@77 -47.38 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:18:25

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB75@0 -47.49 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:20:17

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB75@0 -37.57 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:21:14

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@0 -37.53 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:24:02

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@0 -46.98 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:23:05

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@77 -46.59 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:25:28

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@77 -38.02 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:26:26

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB75@0 -38.09 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:28:17

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB75@0 -46.67 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:27:19

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -46.68 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:31:30

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -37.60 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:32:26

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@215 -47.55 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:33:20

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@215 -38.10 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:34:17

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB216@0 -37.49 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:36:04

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB216@0 -46.60 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:35:07

40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.79 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:38:14

40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -45.78 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:37:11

40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@215 -37.53 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:40:16

40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@215 -46.58 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:39:20

40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB216@0 -47.69 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:41:19

40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB216@0 -37.64 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:42:16

40MHz_15kHz_3780MHz_DFT-s-OFDM QPSK_RB1@0 -46.85 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:43:06

40MHz_15kHz_3780MHz_DFT-s-OFDM QPSK_RB1@0 -38.02 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:44:03

40MHz_15kHz_3780MHz_DFT-s-OFDM QPSK_RB1@215 -38.03 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:45:50

40MHz_15kHz_3780MHz_DFT-s-OFDM QPSK_RB1@215 -46.82 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:44:53

40MHz_15kHz_3780MHz_DFT-s-OFDM QPSK_RB216@0 -45.31 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:46:41

40MHz_15kHz_3780MHz_DFT-s-OFDM QPSK_RB216@0 -38.12 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:47:40

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -38.26 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:30:08

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -47.06 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:29:11

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@105 -47.30 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:31:01

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@105 -37.63 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:31:59

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB100@0 -38.19 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:33:51

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB100@0 -47.36 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:32:53

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.41 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:35:41

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.78 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:34:43

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@105 -37.82 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:37:32

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@105 -47.63 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:36:35

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB100@0 -46.85 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:38:34

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB100@0 -37.31 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:39:31

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB1@0 -47.40 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:40:23

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB1@0 -37.71 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:41:20

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB1@105 -47.01 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:42:12

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB1@105 -38.10 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:43:09

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB100@0 -37.72 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:45:00

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB100@0 -46.77 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:44:03

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -46.60 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:48:50

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -37.62 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:49:46

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@269 -38.00 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:51:36

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@269 -47.54 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:50:39

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB270@0 -37.97 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:53:23

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB270@0 -47.33 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:52:26

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.05 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:54:13

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.81 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:55:09

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@269 -47.67 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:56:01

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@269 -37.83 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:56:58

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB270@0 -47.56 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:57:49

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB270@0 -37.16 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:58:46

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB1@0 -37.40 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 12:00:34

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB1@0 -47.50 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 11:59:38

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB1@269 -37.92 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 12:02:22

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB1@269 -47.15 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 12:01:25

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB270@0 -47.47 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 12:03:12

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB270@0 -38.26 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 12:04:09

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -47.21 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:45:54

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -37.59 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:46:51

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@132 -37.64 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:48:42

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@132 -46.99 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:47:44

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB128@0 -47.25 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:49:35

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB128@0 -38.13 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:50:33

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.15 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:51:26

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.68 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:52:24

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@132 -47.65 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:53:16

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@132 -37.98 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:54:14

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB128@0 -38.15 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:56:05

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB128@0 -46.96 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:55:07

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB1@0 -37.96 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:58:28

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB1@0 -47.07 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:57:31

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB1@132 -47.54 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 13:59:21

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB1@132 -37.87 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:00:19

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB128@0 -37.89 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:02:10

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB128@0 -47.10 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:01:12

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0 -37.36 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:04:01

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0 -46.71 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:03:04

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@161 -37.40 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:05:52

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@161 -47.81 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:04:54

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB162@0 -37.63 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:07:43

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB162@0 -46.45 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:06:46

60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.98 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:09:34

60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.70 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:08:37


60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@161 -47.28 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 14:10:28


60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@161 -37.70 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 14:11:25


60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB162@0 -37.71 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 14:13:24


60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB162@0 -46.39 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 14:12:19


60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB1@0 -46.54 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng

Date: 8.MAY.2024 14:14:18


60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB1@0 -37.85 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng


Date: 8.MAY.2024 14:15:16

60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB1@161 -37.83 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:17:08

60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB1@161 -47.28 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:16:11

60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB162@0 -37.92 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:19:21

60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB162@0 -47.28 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:18:22

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0 -37.67 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:21:37

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0 -46.59 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:20:31

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@188 -45.92 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:22:53

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@188 -37.43 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:23:58

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB180@0 -47.18 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:25:13

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB180@0 -37.99 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:26:17

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.40 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:28:55

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.90 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:27:55

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@188 -47.84 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:30:13

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@188 -37.25 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:31:16

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB180@0 -47.31 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:32:11

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB180@0 -38.03 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:33:09

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@0 -37.92 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:42:08

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@0 -46.97 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:41:08

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@188 -46.67 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:43:07

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@188 -37.77 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:44:05

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB180@0 -46.62 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:45:15

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB180@0 -38.29 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:46:15

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@0 -47.08 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:47:10

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@0 -37.83 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:48:08

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@216 -38.06 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:50:00

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@216 -47.22 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:49:03

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB216@0 -38.19 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:51:58

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB216@0 -47.28 dBm




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:51:00

80MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.85 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:53:49

80MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.97 dBm



ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 8.MAY.2024 14:52:52