



LTE Band 41 , Normal
 1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:16:38

5MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:17:02

5MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:17:26

10MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:18:18

10MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:18:41

10MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:19:04

15MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:20:12

15MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:20:35

15MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:20:58

20MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:22:06

20MHz_Middle_QPSK_1@0(30MHz~27.9GHz)



ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:22:29


20MHz_High_QPSK_1@0(30MHz~27.9GHz)



ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:22:54


LTE Band 66 , Normal
 1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:23:33

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:23:55

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:24:17

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:24:44

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:25:07

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 6.APR.2025 21:25:31

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 6.APR.2025 21:25:58

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 6.APR.2025 21:26:21

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 6.APR.2025 21:26:44

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 6.APR.2025 21:27:10

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 6.APR.2025 21:27:32

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 6.APR.2025 21:27:54

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 6.APR.2025 21:28:20

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 6.APR.2025 21:28:42

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 6.APR.2025 21:29:04

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 6.APR.2025 21:29:30

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 6.APR.2025 21:29:53

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 6.APR.2025 21:30:15

**** END ****