

Test Information:

Sample No.:	2TGQ-2	Test Date:	2024/11/13~2024/11/24
Test Site:	RF	Test Mode:	Transmitting
Tester:	Usain Ou	Test Result:	Pass

Environmental Conditions:

Temperature: (°C):	24.5-26.5	Relative Humidity: (%)	48-52	ATM Pressure: (kPa)	101
-----------------------	-----------	---------------------------	-------	------------------------	-----

Tester: *Usain Ou*

Reviewer: *Jim Cheng*


Spurious Emissions at Antenna Terminal

FCC For 90S

B26_1, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 17:55:27

1.4MHz_Low_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 13.NOV.2024 00:43:14

1.4MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 17:56:00

1.4MHz_High_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 13.NOV.2024 00:44:48

3MHz_Low_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 13.NOV.2024 00:46:27

3MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 17:56:41

3MHz_High_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 13.NOV.2024 00:48:01

3MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 17:57:15

5MHz_Low_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 13.NOV.2024 00:49:44

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 17:57:56

5MHz_High_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 13.NOV.2024 00:51:20

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 17:58:29

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 17:59:10

10MHz_Low_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 13.NOV.2024 00:53:02

15MHz_Low_QPSK_1@0(1GHz~9.24GHz)



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 13.NOV.2024 23:07:21

15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 18:00:20

B26_3, Normal


1RB was the worst case

1.4MHz_Middle_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 13.NOV.2024 23:43:42

1.4MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 18:18:35

3MHz_Middle_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 13.NOV.2024 23:45:39

3MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 18:19:16

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 18:21:28

5MHz_Middle_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 13.NOV.2024 23:53:29

10MHz_Middle_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 13.NOV.2024 23:56:27

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 18:23:15

15MHz_Middle_QPSK_1@0(30MHz~1GHz)



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 18:23:54

15MHz_Middle_QPSK_1@0(1GHz~9.24GHz)



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 13.NOV.2024 23:58:08