


B41, Normal


5MHz_Low_QPSK_25@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:45:06




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:45:15


5MHz_Low_16QAM_25@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:45:32




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:45:41


5MHz_Middle_QPSK_25@0

Occupied Bandwidth

26dB Bandwidth




ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:45:58



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:46:07


5MHz_Middle_16QAM_25@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:46:24


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:46:33


5MHz_High_QPSK_25@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:46:50


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:46:59


5MHz_High_16QAM_25@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:47:15


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:47:24


10MHz_Low_QPSK_50@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:48:22


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:48:31


10MHz_Low_16QAM_50@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:48:49


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:48:58


10MHz_Middle_QPSK_50@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 19:22:51


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 19:23:16


10MHz_Middle_16QAM_50@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 27.NOV.2024 19:31:00


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 27.NOV.2024 19:31:27


10MHz_High_QPSK_50@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:50:16


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:50:25


10MHz_High_16QAM_50@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:50:43


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:50:52


15MHz_Low_QPSK_75@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:56:59


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:57:09


15MHz_Low_16QAM_75@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:57:28


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:57:38


15MHz_Middle_QPSK_75@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:57:58


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:58:08


15MHz_Middle_16QAM_75@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:58:29


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:58:39


15MHz_High_QPSK_75@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 19:19:18


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 19:19:37


15MHz_High_16QAM_75@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 19:20:32


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 24.NOV.2024 19:20:42


20MHz_Low_QPSK_100@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 23:01:01


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 23:01:10


20MHz_Low_16QAM_100@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 23:01:29


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 23:01:38


20MHz_Middle_QPSK_100@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 23:01:59


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 23:02:10


20MHz_Middle_16QAM_100@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 23:02:30


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 23:02:41


20MHz_High_QPSK_100@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 23:03:01


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 23:03:11


20MHz_High_16QAM_100@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 23:03:31


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 23:03:41


5MHz_Middle_16QAM_25@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:46:24


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:46:33


5MHz_High_QPSK_25@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:46:50


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:46:59


5MHz_High_16QAM_25@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:47:15


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:47:24


10MHz_Low_QPSK_50@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:48:22


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:48:131


10MHz_Low_16QAM_50@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:48:49


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:48:158


10MHz_Middle_QPSK_50@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:49:17


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:49:127


10MHz_Middle_16QAM_50@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:49:45


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:49:56


10MHz_High_QPSK_50@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:50:16


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:50:25


10MHz_High_16QAM_50@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:50:43


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:50:52


15MHz_Low_QPSK_75@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:56:59


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:57:09


15MHz_Low_16QAM_75@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:57:28


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:57:38


15MHz_Middle_QPSK_75@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:57:58


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Tester:Usain Ou
Date: 6.NOV.2024 22:58:08


15MHz_Middle_16QAM_75@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Testers:Usain Ou
Date: 6.NOV.2024 22:58:29


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Testers:Usain Ou
Date: 6.NOV.2024 22:58:39


15MHz_High_QPSK_75@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Testers:Usain Ou
Date: 6.NOV.2024 22:58:59


26dB Bandwidth



ProjectNo.:2401Y58158E-RF Testers:Usain Ou
Date: 6.NOV.2024 22:59:09


15MHz_High_16QAM_75@0

Occupied Bandwidth



ProjectNo.:2401Y58158E-RF Testers:Usain Ou
Date: 6.NOV.2024 22:59:29

26dB Bandwidth



ProjectNo.:2401Y58158E-RF Testers:Usain Ou
Date: 6.NOV.2024 22:59:39