

OBDSTAR Technology Co., Ltd

19th floor, Building T1, Hi Park, Luo Zu Community, Shiyan Street, Baoan District,
Shenzhen, Guangdong, China

Date: August 5, 2026

FCC ID: 2AJ2D-MS80PRO

Model Number: MS80 Pro, MS80 G2, MS80 Turbo, MS80 G3 Turbo, MS80 Pro, MS80 Elite, MS80 Lite, MS80 G3, MS80 G3 Pro, MS80 G3 Elite, MotoScan Elite, Moto Diag Elite, MotoDiag Pro, MotoScan Pro


To: Federal Communication Commission
Authorization and Evaluation Division 7435 Oakland Mills Road
Columbia, MD 21048

To Whom It May Concern,

We, **OBDSTAR Technology Co., Ltd** hereby declare that our product (**Motorcycle Diagnostic Tool**) Model Number: **MS80 Pro, MS80 G2, MS80 Turbo, MS80 G3 Turbo, MS80 Pro, MS80 Elite, MS80 Lite, MS80 G3, MS80 G3 Pro, MS80 G3 Elite, MotoScan Elite, Moto Diag Elite, MotoDiag Pro, MotoScan Pro** PCB board, structure and internal of these model(s) are the same, Only the model's name and color different, So no additional models were tested.

Should you have any questions or comments regarding this matter, please have my best attention.

Sincerely,



(Signed)

Name / Title: Hongtao Wang / Manager

Company: OBDSTAR Technology Co., Ltd

Address: 19th floor, Building T1, Hi Park, Luo Zu Community, Shiyan Street, Baoan District, Shenzhen, Guangdong, China

Phone: +86-755-86702171

Fax: +86-755-86707161

E-Mail: xycd@obdstar.cn