

---



## INTERTEK TESTING SERVICE

---

Report No.: 17081166HKG-002

### Equipment Photographs

(Internal)



---



## INTERTEK TESTING SERVICE

---

Report No.: 17081166HKG-002

### Equipment Photographs

(Internal)



---



## INTERTEK TESTING SERVICE

---

Report No.: 17081166HKG-002

### Equipment Photographs

(Internal)





## INTERTEK TESTING SERVICE

---

Report No.: 17081166HKG-002

### Equipment Photographs

(Internal)



---



## INTERTEK TESTING SERVICE

---

Report No.: 17081166HKG-002

### Equipment Photographs

(Internal)



---

## INTERTEK TESTING SERVICE

---

Report No.: 17081166HKG-002

### Equipment Photographs

(Internal)

