



Exhibit: Internal Photos

FCC ID: 2AJLM-UNT1422
IC: 21879-UNT1422

Report File #: 7169001483-000

Client	ARCX Inc.	 Canada
Product	UNT1422	
Standard(s)	RSS 210 Issue 8:2010, Annex 2 FCC Part 15 Subpart 15.225:2016	




Figure 1 – EUT Internal Photo Top

Client	ARCX Inc.	
Product	UNT1422	
Standard(s)	RSS 210 Issue 8:2010, Annex 2 FCC Part 15 Subpart 15.225:2016	




Figure 2 – EUT Internal Photo Top (Without the Shield)

Client	ARCX Inc.	
Product	UNT1422	
Standard(s)	RSS 210 Issue 8:2010, Annex 2 FCC Part 15 Subpart 15.225:2016	




Figure 3 – EUT Internal Photo Bottom

Client	ARCX Inc.	
Product	UNT1422	
Standard(s)	RSS 210 Issue 8:2010, Annex 2 FCC Part 15 Subpart 15.225:2016	




Figure 4 – EUT Internal Photo Bottom (Without the Shield)

Client	ARCX Inc.	 Canada
Product	UNT1422	
Standard(s)	RSS 210 Issue 8:2010, Annex 2 FCC Part 15 Subpart 15.225:2016	




Figure 5 – EUT's Custom Loop Antenna - Top

Client	ARCX Inc.	
Product	UNT1422	
Standard(s)	RSS 210 Issue 8:2010, Annex 2 FCC Part 15 Subpart 15.225:2016	




Figure 6 – EUT's Custom Loop Antenna - Bottom