



FCC Part 22H

LTE Band 5, Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0




1.4MHz_Low_16QAM_6@0




1.4MHz_High_QPSK_1@5



1.4MHz_High_QPSK_6@0




1.4MHz_High_16QAM_1@5




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 11:51:40

1.4MHz_High_16QAM_6@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 11:52:29

3MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 11:53:33

3MHz_Low_QPSK_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 11:54:30

3MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 11:55:27

3MHz_Low_16QAM_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 11:56:24

3MHz_High_QPSK_1@14




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 11:57:19

3MHz_High_QPSK_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 11:58:15

3MHz_High_16QAM_1@14




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 11:59:10

3MHz_High_16QAM_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:00:06

5MHz_Low_QPSK_1@0



ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:01:13


5MHz_Low_QPSK_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 21:16:41

5MHz_Low_16QAM_1@0

5MHz_Low_16QAM_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:03:17




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:04:15

5MHz_High_QPSK_1@24

5MHz_High_QPSK_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:05:13




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:06:11

5MHz_High_16QAM_1@24

5MHz_High_16QAM_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:07:10




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:08:09

10MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:09:43

10MHz_Low_QPSK_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:11:17

10MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:12:38

10MHz_Low_16QAM_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:13:59

10MHz_High_QPSK_1@49




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:15:21

10MHz_High_QPSK_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:16:42

10MHz_High_16QAM_1@49




10MHz_High_16QAM_50@0




LTE B26_2, Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0



1.4MHz_Low_16QAM_6@0




1.4MHz_High_QPSK_1@5




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:27:25

1.4MHz_High_QPSK_6@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:28:19

1.4MHz_High_16QAM_1@5




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:29:13

1.4MHz_High_16QAM_6@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:30:07

3MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:31:13

3MHz_Low_QPSK_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:32:13

3MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:33:14

3MHz_Low_16QAM_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:34:15

3MHz_High_QPSK_1@14




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:35:15

3MHz_High_QPSK_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:36:15

3MHz_High_16QAM_1@14




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:37:14

3MHz_High_16QAM_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:38:18

5MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:39:26

5MHz_Low_QPSK_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 21:20:05

5MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:41:45

5MHz_Low_16QAM_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:42:50

5MHz_High_QPSK_1@24




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:43:54

5MHz_High_QPSK_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:44:58

5MHz_High_16QAM_1@24




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:46:01

5MHz_High_16QAM_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:47:05

10MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:48:35

10MHz_Low_QPSK_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 21:22:49

10MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:52:08

10MHz_Low_16QAM_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:53:32

10MHz_High_QPSK_1@49




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:54:57

10MHz_High_QPSK_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:56:21

10MHz_High_16QAM_1@49




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:57:45

10MHz_High_16QAM_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 13:59:08

15MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 14:00:58

15MHz_Low_QPSK_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 14:02:41

15MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 14:04:27

15MHz_Low_16QAM_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 14:06:11

15MHz_High_QPSK_1@74




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 14:07:56

15MHz_High_QPSK_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 14:09:43

15MHz_High_16QAM_1@74



ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 14:11:30

15MHz_High_16QAM_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 14:13:15


FCC Part 24E

LTE Band 2, Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0




1.4MHz_Low_16QAM_6@0




1.4MHz_High_QPSK_1@5



1.4MHz_High_QPSK_6@0




1.4MHz_High_16QAM_1@5




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:39:37

1.4MHz_High_16QAM_6@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:40:06

3MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:40:42

3MHz_Low_QPSK_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:41:15

3MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:41:49

3MHz_Low_16QAM_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:42:24

3MHz_High_QPSK_1@14




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:42:58

3MHz_High_QPSK_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:43:31

3MHz_High_16QAM_1@14




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:44:04

3MHz_High_16QAM_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:44:36

5MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:45:10

5MHz_Low_QPSK_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:45:41

5MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:46:12

5MHz_Low_16QAM_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:46:42

5MHz_High_QPSK_1@24




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:47:13

5MHz_High_QPSK_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:47:44

5MHz_High_16QAM_1@24




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:48:14

5MHz_High_16QAM_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:48:44

10MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:49:28

10MHz_Low_QPSK_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:50:09

10MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:50:51

10MHz_Low_16QAM_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:51:31

10MHz_High_QPSK_1@49




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:52:13

10MHz_High_QPSK_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:52:55

10MHz_High_16QAM_1@49




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:53:38

10MHz_High_16QAM_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:54:20

15MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:55:14

15MHz_Low_QPSK_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:56:06

15MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:56:59

15MHz_Low_16QAM_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:57:52

15MHz_High_QPSK_1@74




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:58:45

15MHz_High_QPSK_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 22:59:38

15MHz_High_16QAM_1@74




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 23:00:30

15MHz_High_16QAM_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 23:01:21

20MHz_Low_QPSK_1@0



ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 28.JUN.2025 23:02:28

20MHz_Low_QPSK_100@0



ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 21:26:42