

When the temperature of the product exceeds the limit, the electricity indicator will be off, and it can be used after the product cools down.